

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73001
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 9905 - MICHAEL ELLISON
Address: 8200 OAK GROVE RD NEWBURGH, IN

47630

Phone: 812-598-6710

Stock Number: 11345 - 2024 CATALINA 263BHCKLE 5ZT2CARB8RX030716

VIN: 5ZT2CARB8RX030716 HIN:

SER#: 5ZT2CARB8RX030716

Mileage: 0

Work Order Comp: 29 FEB 24

Auth. No:

Dealer #:

Warr. Date: 29 FEB 24

Work Order Date: 04 MAR 24

Inv #: 401707

WO # Job # Description JOB INFORMATION

73001 2 THE WATER HEATER WILL NOT LIGHT
 WATER HEATER WILL NOT LIGHT
 Water heater is trying to ignite, but will not light after a doz.
 trys. Checked for gas flow at water heater. No gas at water
 heater. Checked LP hose at all visible spots. Line is not
 pinched. Cut access hole in underbelly below water heater where
 LP hose attaches to LP block. Lp hose is pinched between frame
 and floor. Cut off LP hose on both sides of pinched area.
 3-6-2024: Turned in parts request for a new LP hose, 6 ft .long.
 Received new LP hose. Installed new hose and checked for leaks.
 No leaks. Resealed underbelly access hole.

73001 1 UNIT HAS HOT SKIN AND GFI WILL NOT TRIP
 TESTED AND UNIT HAD 28 VOLTS ON FRAME TO BUILDING WE TOOK APART
 THE GFI AND TESTED AND TESTED THE NUETRALS IN THE BREAKER BOX AND
 FOUND THERE WAS VOLTAGE FROM THE NUETRAL TO THE GROUNDS BUT WOULD
 NOT LIGHT A TEST LIGHT FROM GROUND TO HOT SO WE CHECKED THE PLUG
 COMING INTO THE TRAILER AND FOUND THE GROUND WAS NOT CONNECTED.

73001 3 BEDROOM CLOSET TRIM HAS STAPLE HOLES
 BEDROOM CLOSET HAS HOLES IN TRIM (NOTED ON DELIVERY)
 All trim around closet shelves have holes that need to be filled.
 Filled all staple holes on corner trim and wall panels with
 matching putty. (5 shelves).

Part No Job# Description PARTS Qty Price Total

APPM65CL 2 ME65CL COLEMAN ROADTRIP CONVERSIO 1.00 63.17 63.17

Claim : 73001

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****

```

```

*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      2    MISC LABOUR CODE (EXTERNAL)          0.30    170.00    51.00
Z990      2    MISC LABOUR CODE (EXTERNAL)          0.19    170.00    32.30
Z990      2    MISC LABOUR CODE (EXTERNAL)          0.81    170.00   137.70
Z990      1    MISC LABOUR CODE (EXTERNAL)          1.44    170.00   244.80
Z990      1    MISC LABOUR CODE (EXTERNAL)          1.06    170.00   180.20
Z990      3    MISC LABOUR CODE (EXTERNAL)          0.10    170.00    17.00

```

```

*****
Job#  Sublet Description          SUBLET          Total
*****
2    HOSE SPLICE

```

```

Parts Total:      63.17
Labour Total:     663.00
Sublet Total:     18.92
Extras Total:      0.00

```

```

>>>>> Claim Total:      745.09

```

Customer Signature: _____

Date: _____