



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73088  
Promised Date:  
20 MAR 24

### CUSTOMER WORK ORDER

WO #: 73088

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: PH  
Location: 0327 BH TO CLOSE

Stock #: 11357  
Stock Desc: 2024 TT KEYSTONE  
SPRINGDALE 261BHC  
Chassis #: 4YDTSGM2XR7103312  
Serial #: 4YDTSGM2XR7103312  
Mileage: 0  
Licence:

Invoice #:  
Date In: 14 MAR 24  
Promised: 30 MAR 24  
Date Sched:  
Completed: 27 MAR 24  
Warr. Date:

#### Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

#### Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #WINTER - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.  
\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*  
UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA  
\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*  
NUMBER OF GALLONS USED \_\_\_\_\_

#### Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JH	N/C

#### Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #WINTER: 0.00**

#### Job #1 - Warranty

COMPLAINT: REAR ENTRY DOOR NEEDS ADJUSTED

CAUSE: Rear entry doorneeds adjusted



Customer #: 1000  
BASDEN'S AMERICAN RV,



CORRECTION: Adjust the door and the door catch. The door now closes properly after adjustment.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00
<b>Subtotal for Job #1:</b>			<b>34.00</b>

**Job #2 - Internal**

COMPLAINT: FURNANCE EXHAUST IS BENT

CAUSE: Furnace vent bent

CORRECTION: Remove furnace vent and clean old sealant out, reposition vent, and seal it up.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	N/C
<b>Subtotal for Job #2:</b>			<b>0.00</b>

**Job #3 - Warranty**

COMPLAINT: PANTRY DOOR WONT LATCH

CAUSE: Pantry door won't latch

CORRECTION: Checked and found door catch was set to deep into door frame, removed door catch and routed out door frame to make door catch be in the right position to let door latch. Reinstalled door catch and doorlatches properly.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00
<b>Subtotal for Job #3:</b>			<b>34.00</b>

Parts Total:	0.00
Labour Total:	68.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>68.00</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 27 Mar 2024

W/O: 73088  
Promised Date: 30 MAR 24



Customer #: 1000  
BASDENS AMERICAN RV,

