



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73110

CUSTOMER WORK ORDER

WO #: 73110

Customer: 1000 - BASDENS AMERICAN

RV -

Tag:

Author: PH

Location: 0331 CHECK PREAUTH

Stock #: 11350

Stock Desc: 2024 5W KEYSTONE

COUGAR SPORT 2400RE

Chassis #: 4YDFCGL24R2505481

Serial #: 4YDFCGL24R2505481

Mileage: 0

Licence:

Invoice #:

Date In: 18 MAR 24

Promised:

Date Sched:

Completed: 28 MAR 24

Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: Checked appliances brakes tire pressure torqued lugs checked electrical system water and plumbing system filled l.p. tanks and ran drop test. Ran channel scan on t.v. Checked doors and drawers. Documented model and serial numbers.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Ran a.f through all lines and fixtures

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THE SWITCH INSIDE THE PANTRY DOOR IS OUT.

CAUSE: Secured switch

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	17.00

Subtotal for Job #1: 17.00

Job #2 - Warranty

COMPLAINT: THE BATHROOM SHOWER NEEDS TO BE SEALED.

CAUSE: Corner of shower is leaking. Applied silicone.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	34.00

Subtotal for Job #2: 34.00

Parts Total: 0.00
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Mar 2024

Customer #: 1000
BASDENS AMERICAN RV,

