



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73191



CUSTOMER WORK ORDER

WO #: 73191

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0405 CHECK PREAUTH

Stock #: 11353
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 1750RD
Chassis #: 4YDTSGG15RW103341
Serial #: 4YDTSGG15RW103341
Mileage: 0
Licence:

Invoice #:
Date In: 26 MAR 24
Promised:
Date Sched:
Completed: 30 MAR 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HRS

CAUSE: PDINTT PDI NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Filled LP tank. Relocated Brake-away switch to make room for hitch brackets. Installed new battery box. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 75 psi. Checked roof and sealed a few air bubbles. Operated all stab jacks. Checked power cord. Checked entrance door and all compartment doors. Checked awning. Checked awning lights. Checked all interior lights. Checked converter output. Checked all windows and blinds. Checked all cabinets and drawers. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Applied all company decals. Filled fresh water tank. System did not have antifreeze in it. Checked all water lines and faucets for leaks. Checked all traps and drain lines. Performed LP drop test and set LP pressure at 10 in.wc. Filled all holding tanks and checked monitor panel. Grey tank not reading on monitor panel. Checked Refrigerator, Microwave, Range, Furnace and Water Heater. Drained all holding tanks and moved outside to await part ordered. Took pictures and recorded all serial numbers. Checked TV antenna with test TV. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: GFI WILL NOT RESET

CAUSE: GFCI WILL NOT RESET

CORRECTION: Removed bad GFCI receptical. Turned in parts request for a new receptical. 3/9/2024: Received new GFCI outlet. Installed new GFCI outlet. Checked operation at all GFCI outlets. All good.



Customer #: 1000
BASDEN'S AMERICAN RV,



Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	0.00
Z990	MISCELLANEOUS REPAIR	DKM	51.00

Parts				
Part #	Description	Qty	Price	Total
528952	Recept - GFCI - Self Test - 15A - 12	1.00	16.39	16.39

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-GFCI OUTLET	1.00	18.60	18.60

Subtotal for Job #1: 85.99

Job #2 - Warranty

COMPLAINT: FRONT DOOR SIDE TOP MARKER LIGHT HAS WATER IN IT NOD

CAUSE: FRONT DOOR SIDE TOP MARKER LIGHT HAS WATER IN IT (NOD)

CORRECTION: Removed light lens and dried out lens and light. Cleaned off old silicone. Added putty tape to fill in low areas around light. Remounted lens. Sealed all around light with clear silicone.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: GREY TANK DOES NOT READ ON MONITOR PANEL

CAUSE: GREY TANK DOES NOT READ ON MONITOR PANEL

CORRECTION: Checked all wires at grey tank. Found that ground wire was pulled too tight and pulled out of crimp connector. Rerouted ground wire and added new crimp connector.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	51.00

Subtotal for Job #3: 51.00

Parts Total: 16.39
Labour Total: 136.00
Sublet Total: 0.00
Extras Total: 18.60

WORK ORDER TOTAL: 170.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Apr 2024

Customer #: 1000
BASDEN'S AMERICAN RV,

