

Pre-Authorization

Pre-Authorization number PA03652341 Reference no: 73227 Status: Approved Approved by kiddz Approved date 4/23/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTCGR20RV505602
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6200206B	LP Bottle - Replac	0.00	0.20	0.20		1	0.20	Complaint:ONE LP TANK WON'T FILL Cause:ONE LP TANK WILL NOT FILL Correction:Filled new Lp tank. 6 gals LP KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB
2	2300612B	Entrance Door - H	0.00	0.20	0.20		1	0.30	Complaint:THE ENTRANCE DOOR DEAD BOLT WILL NOT LOCK Cause:ENTRANCE DOOR DEAD BOLT WILL NOT LOCK Correction:Cleared out material behind latch plate so that dead bolt plunger would extend and lock
3	1200508B	Coupler, Weld On	0.00	0.20	0.20		1	1.00	Complaint:THE PET RING PULLED OFF OF THE FRAME MOUNT Cause:THE PET RING ISPULLED OFF OF FRAME. Correction:Factory mounted pet ring with too small screws and screw heads pulled through mounting holes. Remounted pet ring with screws that had larger heads.
4	4206206B	Stereo/Tape/CD F	0.00	0.10	0.10		1	0.10	Complaint:RADIO REMOTE DOES NOT WORK Cause:RADIO REMOTE DOES NOT WORK. Correction:(4-15-2024) Turned in parts request for a new radio remote. Put new Remote in unit. Put old Remote on warranty shelf. KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB

Pre-Authorization number PA03652341 0.70

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company