



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73227

CUSTOMER WORK ORDER

WO #: 73227

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0425 CHECK PREAUTH

Stock #: 11361
Stock Desc: 2024 TT KEYSTONE
COUGAR HALF-TON 33RLI
Chassis #: 4YDTCGR20RV505602
Serial #: 4YDTCGR20RV505602
Mileage: 0
Licence:

Invoice #:
Date In: 30 MAR 24
Promised:
Date Sched:
Completed: 24 APR 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT PDI - NEW - TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Filled (1) LP tank. The other would not take LP. Installed new battery box. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Checked power cord. Checked converter output. Checked Entrance door and all Compartment doors. Checked Roof. Checked both Patio awnings. Operated Power Stab jacks. Checked all interior lights. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Applied all company decals. Checked all windows and blinds. Checked all cabinets and drawers. Chceked Bed, couch and recliners. Took pictures and recorded all serial numbers. Removed Winterized Labels Filled fresh water tank and flushed antifreeze from all water lines and faucets. Performed LP drop test and set LP pressure at 11 in.wc. Filled all holding tanks and checked monitor panel. Checked Refrigerator, Range, Furnace, Microwave, Fireplace and Air Conditioner. Filled all holding tanks and checked monitor panel. Dumped all holding tanks. Checked TV Antenna, rear TV and all antenna outlets. Moved unit to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ONE LP TANK WON'T FILL

CAUSE: ONE LP TANK WILL NOT FILL

CORRECTION: Filled new Lp tank. 6 gals LP



Customer #: 1000
BASDEN'S AMERICAN RV,



Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00

Parts				
Part #	Description	Qty	Price	Total
66-4907	L.P.CYLINDER 30 LB. PW	1.00	80.50	80.50
Subtotal for Job #1:				114.50

Job #2 - Warranty

COMPLAINT: THE ENTRANCE DOOR DEAD BOLT WILL NOT LOCK

CAUSE: ENTRANCE DOOR DEAD BOLT WILL NOT LOCK

CORRECTION: Cleared out material behind latch plate so that dead bolt plunger would extend and lock.

Labor				
Code	Description	Mechanic	Total	
Z990	MISCELLANEOUS REPAIR	DKM	34.00	
Subtotal for Job #2:				34.00

Job #3 - Warranty

COMPLAINT: THE PET RING PULLED OFF OF THE FRAME MOUNT

CAUSE: THE PET RING IS PULLED OFF OF FRAME.

CORRECTION: Factory mounted pet ring with too small screws and screw heads pulled through mounting holes. Remounted pet ring with screws that had larger heads.

Labor				
Code	Description	Mechanic	Total	
Z990	MISCELLANEOUS REPAIR	DKM	34.00	
Subtotal for Job #3:				34.00

Job #4 - Warranty

COMPLAINT: RADIO REMOTE DOES NOT WORK

CAUSE: RADIO REMOTE DOES NOT WORK.

CORRECTION: (4-15-2024) Turned in parts request for a new radio remote. Put new Remote in unit. Put old Remote on warranty shelf.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	8.50
Z990	MISCELLANEOUS REPAIR	DKM	8.50
Z990	MISCELLANEOUS REPAIR	DKM	0.00

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-RADIO REMOTE	1.00	17.89	17.89
Subtotal for Job #4:				34.89



Customer #: 1000
BASDENS AMERICAN RV,



Parts Total:	80.50
Labour Total:	119.00
Sublet Total:	0.00
Extras Total:	17.89
WORK ORDER TOTAL:	217.39

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 24 Apr 2024

Customer Signature : _____

Customer Work Order



Customer #: 1000
BASDEN'S AMERICAN RV,

