



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73256  
Promised Date:  
24 APR 24

### CUSTOMER WORK ORDER

WO #: 73256

Customer: 54689 - DRAPER, GLYN -  
812-664-6594

Tag: CAM - SCREEN DOOR ORDERED  
4-4-24

Author: CAM

Location: 0513 CHECK STATUS WITH  
DH

Stock #: 11121

Stock Desc: 2024 TT FOREST RIVER  
CHEROKEE 304BH

Chassis #: 4X4TCKF25RX162004

Serial #: 4X4TCKF25RX162004

Mileage:

Licence:

Invoice #:

Date In: 01 APR 24

Promised: 30 APR 24

Date Sched:

Completed: 10 MAY 24

Warr. Date: 25 APR 24

#### Job #1 - Warranty

COMPLAINT: BOTTOM OF SCREEN DOOR IS BROKEN

CAUSE: screen door

CORRECTION: had to measure door height to put in hinge screws, then transferred door lock and door handle slide, all good.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

#### Parts

Part #	Description	Qty	Price	Total
F100307275	ENTRY DOOR, SCREEN DOOR ONLY - 26" X	1.00	111.06	111.06

#### Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-SCREEN DOOR	1.00	190.00	190.00

**Subtotal for Job #1: 335.06**

#### Job #2 - Internal

COMPLAINT: ROB DOOR OFF LOT UNIT FOR DELIVERY.

CAUSE: screen door

CORRECTION: had to rob screen door on lot for delivery, took out of 5zt2ckec9ry033364 and installed on delivery unit.

NOTE: PARTS GO ON STOCK # 11366 CHEROKEE WOLF DEN.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #2: 0.00**

Customer #: 54689  
DRAPER, GLYN



W/O: 73256  
Promised Date: 30 APR 24

Parts Total:	111.06
Labour Total:	34.00
Sublet Total:	0.00
Extras Total:	190.00
<b>WORK ORDER TOTAL:</b>	<b>335.06</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 10 May 2024



Customer #: 54689  
DRAPER, GLYN

