

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1874514
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAEC8RK006816
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BHX
EVAN REBAR		DEALER RO #	73274
1435 CRESENT ST		CLAIM START DATE	04/05/2024
Evansville, IN 47720		CLAIM END DATE	01/01/1900
USA			

Retail Date of Purchase	01/27/2024	WARRANTY EXPIRATION DATE	01/27/2025
-------------------------	------------	--------------------------	------------

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	SB-456-01-00-004506	51-1722 – ROOF MOUNT SOLAR INLET (AURORA & CATALINA) - INSPECTION AND PERFORM REMEDY - Technical Service Bulletin/Sealant/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-04-05 16:10:22 :: 51-1722 ROOF MOUNT SOLAR INLET Recall Took pics. Removed damaged solar inlet. Installed new inlet. Put alpha back on and took pics.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$85.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$85.00
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 2	Operation Code	Operational Description		
	RC-003-22-00-004526	24V254, 2024-214 - CHARGE LINE OVERCURRENT PROTECTION - INSPECTION AND REMEDY - Recall/Electrical/Rewire/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-04-09 08:44:04 :: 24V254 CHARGE LINE LACKING OVERCURRENT PROTECTION Recall Move wires where they said to. Took pics			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
	Notes			
	AUTHORIZED AS REQUESTED			

Submitted	Labor Amt	\$119.00	Approved	Labor Amt	\$119.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$119.00		Total	\$119.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	