

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73278
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 51071 - JEFFREY A. MARTIN
Address: 7819 CHAPEL HILL DR EVANSVILLE, IN

47712

Phone: 812-204-4334

Stock Number: 10742 - 2023 FREEDOM EXPRESS 226RBS 5ZT2FEMB8PW027162

VIN: 5ZT2FEMB8PW027162 HIN:

SER#: 5ZT2FEMB8PW027162

Mileage: 0

Work Order Comp: 06 APR 24

Auth. No:

Dealer #:

Warr. Date: 09 MAR 24

Work Order Date: 03 APR 24

Inv #: 402756

WO # Job # Description JOB INFORMATION

73278 2 CUSTOMER ADVISES THAT THE INSDIE LOCK (DEADBOLT) WILL NOT LOCK
FROM THE INSIDE.
DOOR HANDLE
Removed damaged door handle. Installed new door handle.

73278 1 CUSTOMER ADVISES THAT THERE IS A WATER LEAK AT THE BACK SIDE OF
THE WATER HEATER. THIS IS ON THE INSIDE. CUSTOMER NOTICED AFTER
UNIT WAS DEWINTERIZED.
CONE WASHER
Pressurized water system. Turned on water pump. Let water water
heater heat up. Noticed small amount of water coming out of line
going into water pump. Removed line and noticed cone washer is
not sealing. Replaced cone washer. Pressurized system. No more
leaks present.

73278 3 CUSTOMER WOULD LIKE TO HAVE THE FUNCTION OF THE WATER HEATER
TESTED ON ELECTRIC. CUSTOMER TURNED IT ON, BUT IT SEEMED LIKE IT
WAS TAKING A LONG TIME TO WARM UP.
loose wire not connected
Plugged unit into shore power. Verified waterheater was full.
Turned on switch. Removed rear panel. Cord is plugged into
outlet. Checked power going to outlet. Removed panel on outside
of water heater. Checked continuity through electric heating
element. Checked fuses. Noticed yellow wire had come loose from
relay. Secured wire. Let water heater get to operating temp.

Claim : 73278

 WO # Job # Description JOB INFORMATION

 Part No Job# Description PARTS Qty Price Total

 540114 2 GLOBAL ULTRA M PRO DOOR LOCK 1.00 39.97 39.97
 602317 1 CONE WASHER SWIVEL SEAL 1.00 0.18 0.18

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 170.00 51.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.50 170.00 85.00

Parts Total: 40.15
 Labour Total: 170.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 210.15

Customer Signature: _____

Date: _____