



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73302



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 73302

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0430 BACK UP

Stock #: 11362

Stock Desc: 2024 TT COACHMEN

CATALINA 283FEDSLE

Chassis #: 5ZT2CATB4RX031595

Serial #: 5ZT2CATB4RX031595

Mileage: 0

Licence:

Invoice #:

Date In: 05 APR 24

Promised:

Date Sched:

Completed: 26 APR 24

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI new trailer

CORRECTION: PDI new trailer

Checked water and plumbing systems, electrical system, LP system...leak down test passed. Checked interior and exterior, checked lights and running gear.

Adjusted entry door to open and close... adjust door catch.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BATHROOM DOOR HITTING FRAME

CAUSE: Bathroom door hitting frame

CORRECTION: Readjusted latch and catch on bathroom door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	34.00

Subtotal for Job #1: 34.00

Job #2 - Internal

COMPLAINT: BLIND IN BEDROOM IS DAMAGED

CAUSE: Blind in bedroom damaged

CORRECTION: Repair valance and blind.

Printed On: 4/26/2024 8:53:10AM

© 2024 Integrated Dealer Systems



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 34.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 34.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Apr 2024

W/O: 73302



Customer #: 1000
BASDEN'S AMERICAN RV,

