

Pre-Authorization

Pre-Authorization number PA03652753 Reference no: 73307 Status: Approved Approved by maist Approved date 4/23/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGG13RW103919
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5101906A	Light, Clearance	0.00	0.80	0.50		1	0.20	Complaint:RIGTH TURN SIGNAL DOES NOT WORK Cause:Right turn signal or brake light doesn't work Correction:Remove light, fish loose brake light / turn signal wire out of hole. Reattach wire, clean old silicone from side of camper. Reinstall light and silicone around light.
2	3200606B	Door - Interior Fol	0.00	0.30	0.30		1	0.10	Complaint:BATHROOM DOOR WILL NOT CATCH Cause:Bathroom door won't latch Correction:Remove catch, reshape hole in frame and reattach catch
					0.80				

Pre-Authorization number PA03652753

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company