

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73311
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 24980 - DAVID ANGLIN
Address: 4347 STATE ROUTE 56 E
SEBREE, KY
42455

Phone: 270-339-6845

Stock Number: 11141 - 2023 COUGAR 316RLS 4YDFCGR24P2501614

VIN: 4YDFCGR24P2501614 HIN: SER#: 4YDFCGR24P2501614

Mileage: 0 Work Order Comp: 17 APR 24

Auth. No: Dealer #: 1194

Warr. Date: 27 OCT 23 Work Order Date: 08 APR 24 Inv #: 403144

WO # Job # Description JOB INFORMATION

73311 2 COLD WATER DRIPPING FROM CONNECTION ON WASHER DRYER AREA.
CUSTOMER INSTALLED A VALVE.
cold valve leaking at washer.
HOOKED UP WATER AND TESTED AND COLD SIDE IS LEAKING, TOOK OFF
ACCESS PANEL AND HAD TO CUT LINES AND PULL OUT BOTH VALVES TO GET
TO ACCESS NUT AND CUT OFF CLAMP, INSTALLED NEW VALVE AND PUT VALVE
BACK IN PLACE AND CLAMP DOWN, PUT BACK IN WALL AND PUT BOTH LINES
BACK TOGETHER, TESTED AGAIN AND THIS VALVE LEAKS ALSO, HAD TO ORDER
NEW VALVE, WILL NEED TO DO THIS PROCESS AGAIN, WAITING ON PARTS. did
same process as before and put panel back in place, no leaks
this time, all good.

73311 3 MOTION LIGHT KEEPS GOING ON AND OFF EVERY 15 SEC. CUSTOMER
UNHOOKED
motion light by stairs
took out old light and cut wires and installed new light and
wired up.

Part No Job# Description PARTS Qty Price Total

403404 2 Fitting - Plastic - Washer Valve 1.00 6.65 6.65
8474 2 1/2" X 1/2" BARBED NIPPLE - BRASS 2.00 6.30 12.60
51132 2 1/2" BRASS PEX COUPLING 2.00 1.53 3.06
10-0236 2 16051 1/2" x 5' PEX STICK 1.00 3.77 3.77
403405 2 Fitting - Plastic - Washer Valve 1.00 6.65 6.65

Claim : 73311

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
592487        3   Light - LED - Motion Sensor - Cou  1.00      7.58      7.58

```

```

*****
Lab Code     Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990         2   MISCELLANEOUS REPAIR          0.00    170.00      0.00
Z990         2   MISCELLANEOUS REPAIR          1.00    170.00    170.00
Z990         2   MISCELLANEOUS REPAIR          0.00    170.00      0.00
Z990         2   MISCELLANEOUS REPAIR          0.00    170.00      0.00
Z990         3   MISCELLANEOUS REPAIR          0.30    170.00     51.00

```

```

Parts Total:      40.31
Labour Total:     221.00
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>>> Claim Total:      261.31

```

Customer Signature: _____

Date: _____