



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73338
Promised Date:
20 APR 24

CUSTOMER WORK ORDER

WO #: 73338 (Appointment Date: 10 APR 2024 - Time: 04:00pm)

Customer: 53530 - SCHWARTZ, DUSTIN Stock #: 11146

M. - Stock Desc: 2023 TT KEYSTONE

Tag: PH - PARTS ORDERED. COUGAR HALF-TON 26RBS

Author: PH Chassis #: 4YDTCGM21PL500604

Location: 0425 CHECK PREAUTH Serial #: 4YDTCGM21PL500604

Mileage: 0

Licence:

Invoice #:

Date In: 10 APR 24

Promised: 30 APR 24

Date Sched:

Completed: 24 APR 24

Warr. Date: 15 APR 23

Job #1 - Internal

COMPLAINT: SLIDE ROOM IS GETTING STUCK OUT. CUSTOMER HAD IT HERE IN DECEMBER FOR SAME ISSUE AND WE COULD NOT REPLICATE. HE HAS VIDEO SHOWING IT HAPPENING

CAUSE: Got it to stop couple times.

CORRECTION: Replaced the relays in the panel in front compartment.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Z990	MISCELLANEOUS REPAIR	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
FOAZ14N089A	FORD RELAY	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: REAR ENTRY DOOR HAS A SCREW THAT IS HITTING THE FRAME AND IS MAKING AN INDENTION

CORRECTION: adjusted the door tightened the crews and painted the scratches on the frame

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: UNDER THE KITCHEN SINK WE FIXED A LEAK, THERE IS STILL A DRIP ON THE RIGHT SIDE OF THE SINK AT THE WATER LINE

CAUSE: The sink tub was leaking where it meets the countertop

CORRECTION: I added brackets to hold the sink tub and resealed.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	0.00



Customer #: 53530
SCHWARTZ, DUSTIN M.

Z990 MISCELLANEOUS REPAIR BRM 34.00
Subtotal for Job #3: 34.00

Job #4 - Internal

COMPLAINT: SOFT SPOT IN FLOOR IN FRONT OF FRIDGE

CORRECTION: Denny Pete and I all checked the floor and did not find a bad spot or anything rotten.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: THE OUTSIDE SHOWER IN THE DOCKING AREA THE FAUCET LEAKS

CORRECTION: REMOVED THE OLD DOCKING STATION AND INSTALLED NEW AND HOOKED UP AND SEALED THEN HOOKED UP WATER AND TESTED FOR LEAKS . FOUND NO LEAKS

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	170.00

Parts

Part #	Description	Qty	Price	Total
613402	Cover - Convenience Center - Docking	1.00	115.56	115.56

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-COVER	1.00	22.51	22.51

Subtotal for Job #5: 308.07

Parts Total: 115.56
Labour Total: 204.00
Sublet Total: 0.00
Extras Total: 22.51
WORK ORDER TOTAL: 342.07

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Apr 2024

W/O: 73338
Promised Date: 30 APR 24



Customer #: 53530
SCHWARTZ, DUSTIN M.

