

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73360
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 53705 - JEFFREY A. KIDD
Address: 12140 BILLET LN LAWRENCEVILLE, IL

62439

Phone: 618-928-7448

Stock Number: 11249 - 2023 SPRINGDALE 335BH 4YDTSGR23P3100670

VIN: 4YDTSGR23P3100670 HIN:

SER#: 4YDTSGR23P3100670

Mileage: 0

Work Order Comp: 24 APR 24

Auth. No:

Dealer #: 1194

Warr. Date: 05 JUN 23

Work Order Date: 12 APR 24

Inv #: 403417

WO # Job # Description JOB INFORMATION

73360 1 THE 110V OUTLET IN THE MASTER BEDROOM IS NOT WORKING. CUSTOMER
 WAS GOING TO REPLACE GFCI, BUT THE ONE HE HAD WAS THE WRONG SIZE.
 gfci outlet not working
 went in and checked outlet and it was fine but would not fit in
 box,old outlet could not be found,filled out sheet to get new
 outlet,had to guess which outlet because they make 3 different
 ones and we dont have original,screw was broken off in box,so i
 had to take out wires to take box out of wall,got screw out and
 had to put back in wall and wire back up until we get new
 outlet,parts are on order.got the right gfi took old one out and
 wired up new one had to find new screw since bottom one was
 broke,screwed in and tested all good.

73360 2 THE WOOD IS SPLINT IN ONE OF THE DINING BENCHES UNDER CUSHION
 dining wood split
 took pictures and took out board and cut down wood to make new
 one,installed with 1 brackets,all good.

73360 4 DOOR INTO BUNKHOUSE THE CLOSURE SNAP HAS COME OUT
 snap closure
 installed new snap closure.

73360 5 COUCH HAS STORAGE UNDER AND AND WILL NOT POP BACK IN WHEN YOU
 OPEN IT UP
 latch for door under couch
 had to move latch because it was not close to latch to work,moved

Claim : 73360

 WO # Job # Description JOB INFORMATION

 latch to catch door not it stays up.

 Part No Job# Description PARTS Qty Price Total

 529455 1 Recept - GFI - Self Test - 15A - 1.00 19.76 19.76

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISCELLANEOUS REPAIR 0.00 170.00 0.00
 Z990 1 MISCELLANEOUS REPAIR 0.50 170.00 85.00
 Z990 2 MISCELLANEOUS REPAIR 0.40 170.00 68.00
 Z990 4 MISCELLANEOUS REPAIR 0.20 170.00 34.00
 Z990 5 MISCELLANEOUS REPAIR 0.20 170.00 34.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-OUTLET 1.00 18.60 18.60

Parts Total: 19.76
 Labour Total: 221.00
 Sublet Total: 0.00
 Extras Total: 18.60

>>>> Claim Total: 259.36

Customer Signature: _____

Date: _____