



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73360



Customer #: 53705
KIDD, JEFFREY A.



CUSTOMER WORK ORDER

WO #: 73360 (Appointment Date: 12 APR 2024 - Time: 02:00pm)

Customer: 53705 - KIDD, JEFFREY A. -
618-928-7448

Tag:

Author: PH

Location: 0425 FINAL NEED CLOSED
COPY

Stock #: 11249

Stock Desc: (11249) 2023 KEYSTONE
SPRINGDALE 335BH

Chassis #: 4YDTSGR23P3100670

Serial #: 4YDTSGR23P3100670

Mileage:

Licence:

Invoice #:

Date In: 12 APR 24

Promised:

Date Sched:

Completed: 24 APR 24

Warr. Date: 05 JUN 23

Job #1 - Warranty

COMPLAINT: THE 110V OUTLET IN THE MASTER BEDROOM IS NOT WORKING. CUSTOMER WAS GOING TO REPLACE GFCI, BUT THE ONE HE HAD WAS THE WRONG SIZE.

CAUSE: gfci outlet not working

CORRECTION: went in and checked outlet and it was fine but would not fit in box, old outlet could not be found, filled out sheet to get new outlet, had to guess which outlet because they make 3 different ones and we don't have original, screw was broken off in box, so I had to take out wires to take box out of wall, got screw out and had to put back in wall and wire back up until we get new outlet, parts are on order. got the right gfci took old one out and wired up new one had to find new screw since bottom one was broke, screwed in and tested all good.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	0.00
Z990	MISCELLANEOUS REPAIR	DGH	85.00

Parts

Part #	Description	Qty	Price	Total
529455	Recept - GFI - Self Test - 15A - 125	1.00	19.76	19.76

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-OUTLET	1.00	18.60	18.60

Subtotal for Job #1: 123.36

Job #2 - Warranty

COMPLAINT: THE WOOD IS SPLINT IN ONE OF THE DINING BENCHES UNDER CUSHION

CAUSE: dining wood split

CORRECTION: took pictures and took out board and cut down wood to make new one, installed with I brackets, all good.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	68.00

Subtotal for Job #2: 68.00

Job #3 - External

Transferred to BAS*73468 on 24 APR 24

Estimate amount was 0.00

CUSTOMER HAS TRADED TRUCKS SINCE PURCHASING TRAILER. HE WOULD LIKE TO HAVE THE

Printed On: 4/24/2024 10:18:34AM

© 2024 Integrated Dealer Systems



HITCH RESET FOR HIS NEW TRUCK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DOOR INTO BUNKHOUSE THE CLOSURE SNAP HAS COME OUT

CAUSE: snap closure

CORRECTION: installed new snap closure.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	34.00

Subtotal for Job #4: 34.00

Job #5 - Warranty

COMPLAINT: COUCH HAS STORAGE UNDER AND AND WILL NOT POP BACK IN WHEN YOU OPEN IT UP

CAUSE: latch for door under couch

CORRECTION: had to move latch because it was not close to latch to work,moved latch to catch door not it stays up.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	34.00

Subtotal for Job #5: 34.00

Parts Total: 19.76
Labour Total: 221.00
Sublet Total: 0.00
Extras Total: 18.60
WORK ORDER TOTAL: 259.36

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Apr 2024

W/O: 73360

Customer #: 53705
KIDD, JEFFREY A.

