

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73380
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50948 - DONALD H. BRADLEY, JR
Address: 949 OSAGE DR HENDERSON, KY

42420

Phone: 270-454-4853

Stock Number: 11307 - 2024 CATALINA 243RBSLE 5ZT2CANB1RU042729

VIN: 5ZT2CANB1RU042729 HIN:

SER#: 5ZT2CANB1RU042729

Mileage: 0

Work Order Comp: 14 MAY 24

Auth. No:

Dealer #:

Warr. Date: 12 APR 24

Work Order Date: 15 APR 24

Inv #: 404338

WO # Job # Description JOB INFORMATION

73380 1 DECALS ARE BUBBLING ON THE OFF DOOR SIDE
 decals Decals
 took off decal on front and put on new one and messed it
 up, filled out sheet to get new decal, this was suppose to go to
 brett. Removed 6 decals and cleaned off glue. Installed 6 decals
 and heat up to make smooth.

73380 2 RECALL FOR SOLAR INLET LEAKING
 recall solar inlet
 cut rubber off of outlet and took out screws and unplugged wires
 and took off 12 volt wires, cut the rest of rubber off of roof and
 installed new inlet hooked up 12 volt wires, installed buytel tape
 and screwed into place then put dicor all around plate.

73380 3 FIX DEAD BOLT WONT LOCK
 deadbolt
 latch catch was upside down turnrd over and it works fine now.

73380 4 CHECK THAT SOLAR IS CHARGING BATTERY. CUSTOMER STATES THAT HE
 PARKS IN FULL SUN AND THE BATTERY STILL DIES
 battery not charging from solar
 when i did recall wire from positive side fell out, took out
 controller and took off positive sides of wires to reset
 controller, put wires back in and it worked, tested inside and
 outside in sun and it is charging now.

Claim : 73380

 WO # Job # Description JOB INFORMATION

73380 5 HADRAIL HAS A STRIPPED SCREW AT THE TOP OF IT
 handrail
 screw was not stripped ,they were not in all the way checked all
 of them.

73380 6 OUTSIDE SHOWER HAS GAPS OROUND MOUNTING FLANGE THAT ARENT SEALED
 outside shower
 there is no gaps around shower only thing the gap is in is the
 door hinge.all good.

Part No	Job#	Description	PARTS	Qty	Price	Total
F100418605	1	DECAL #12 CATALINA		1.00	5.58	5.58
F100418602	1	DECAL #7 - CATALINA		1.00	8.82	8.82
F100418601	1	DECAL #6 - CATALINA		1.00	12.64	12.64
F100418599	1	DECAL #4 - CATALINA		2.00	7.12	14.24
F100418597	1	DECAL #2A - CATALINA		1.00	5.81	5.81
F100418579	1	DECAL #14 - CATALINA		1.00	10.02	10.02
F100530500	2	CABLE ENTRY ROOF PLATE FOR SOLAR		1.00	9.49	9.49
13-1320	2	PW HAPS FREE SELF-LEVELING DICOR		1.00	7.31	7.31

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.80	170.00	136.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.00	170.00	170.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.04	170.00	6.80
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.46	170.00	78.20
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	1	UPS-DECALS		1.00	17.30	17.30

Parts Total: 73.91
 Labour Total: 561.00
 Sublet Total: 0.00
 Extras Total: 17.30

>>>> Claim Total: 652.21

Customer Signature: _____

Date: _____