



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73380
Promised Date:
20 APR 24

CUSTOMER WORK ORDER

WO #: 73380

Customer: 50948 - BRADLEY, JR,
DONALD H. - 270-454-4853
Tag: BH - DECALS ORDERED. 4-15
Author: PH
Location: 0515 CHECK PREAUTH

Stock #: 11307
Stock Desc: 2024 TT COACHMEN
CATALINA 243RBSLE
Chassis #: 5ZT2CANB1RU042729
Serial #: 5ZT2CANB1RU042729
Mileage: 0
Licence:

Invoice #:
Date In: 15 APR 24
Promised: 30 APR 24
Date Sched:
Completed: 14 MAY 24
Warr. Date: 12 APR 24

Job #1 - Warranty

COMPLAINT: DECALS ARE BUBBLING ON THE OFF DOOR SIDE

CAUSE: decals
Decals

CORRECTION: took off decal on front and put on new one and messed it up, filled out sheet to get new decal, this was suppose to go to Brett.
Removed 6 decals and cleaned off glue. Installed 6 decals and heat up to make smooth.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	136.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	170.00

Parts

Part #	Description	Qty	Price	Total
9193	DECAL #12 CATALINA	1.00	5.58	5.58
9194	DECAL #7 - CATALINA	1.00	8.82	8.82
9195	DECAL #6 - CATALINA	1.00	12.64	12.64
9196	DECAL #4 - CATALINA	2.00	7.12	14.24
9197	DECAL #2A - CATALINA	1.00	5.81	5.81
9198	DECAL #14 - CATALINA	1.00	10.02	10.02

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECALS	1.00	17.30	17.30

Subtotal for Job #1: 380.41

Job #2 - Warranty

COMPLAINT: RECALL FOR SOLAR INLET LEAKING

CAUSE: recall solar inlet

CORRECTION: cut rubber off of outlet and took out screws and unplugged wires and took off 12 volt wires, cut the rest of rubber off of roof and installed new inlet hooked up 12 volt wires, installed buytel tape and screwed into place then put dicor all around plate.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	6.80
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	78.20

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 50948
BRADLEY, JR, DONALD H.



F100530500	CABLE ENTRY ROOF PLATE FOR SOLAR SYSTEM	1.00	9.49	9.49
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	7.31	7.31

Subtotal for Job #2: 101.80

Job #3 - Warranty

COMPLAINT: FIX DEAD BOLT WONT LOCK

CAUSE: deadbolt

CORRECTION: latch catch was upside down turnrd over and it works fine now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

Subtotal for Job #3: 34.00

Job #4 - Warranty

COMPLAINT: CHECK THAT SOLAR IS CHARGING BATTERY. CUSTOMER STATES THAT HE PARKS IN FULL SUN AND THE BATTERY STILL DIES

CAUSE: battery not charging from solar

CORRECTION: when i did recall wire from positive side fell out,took out controller and took off positive sides of wires to reset controller,put wires back in and it worked,tested inside and outside in sun and it is charging now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Subtotal for Job #4: 85.00

Job #5 - Warranty

COMPLAINT: HADRAIL HAS A STRIPPED SCREW AT THE TOP OF IT

CAUSE: handrail

CORRECTION: screw was not stripped ,they were not in all the way checked all of them.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	17.00

Subtotal for Job #5: 17.00

Job #6 - Warranty

COMPLAINT: OUTSIDE SHOWER HAS GAPS AROUND MOUNTING FLANGE THAT ARENT SEALED

CAUSE: outside shower

CORRECTION: there is no gaps around shower only thing the gap is in is the door hinge.all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

W/O: 73380
Promised Date: 30 APR 24



Customer #: 50948
BRADLEY, JR, DONALD H.



Subtotal for Job #6: 34.00

Job #7 - Internal

COMPLAINT: DONNIE MESSED UP A DECAL

CAUSE: Decals

CORRECTION: Remove 6 decals and clean off glue. Install 6 decals and heat up to make smooth

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Parts

Part #	Description	Qty	Price	Total
F100418579	GRAPHIC, #14 ODS "CATALINA" LOGO 202	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECAL	1.00	N/C	N/C

Subtotal for Job #7: 0.00

Parts Total: 73.91
Labour Total: 561.00
Sublet Total: 0.00
Extras Total: 17.30
WORK ORDER TOTAL: 652.21

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 May 2024

W/O: 733380
Promised Date: 30 APR 24



Customer #: 50948
BRADLEY, JR, DONALD H.

