



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73447
Promised Date:
20 APR 24



CUSTOMER WORK ORDER

WO #: 73447

Customer: 54410 - GURDO, JR,
ARTHUR SAMUEL - 618-384-8313
Tag: BH - PARTS ORDERED 5-1
Author: BH
Location: 0610 BH TO CLOSE

Stock #: 10913
Stock Desc: 2023 TT FOREST RIVER
CHEROKEE WOLF PUP 18TO
Chassis #: 5ZT2CKGC2PY028887
Serial #: 5ZT2CKGC2PY028887
Mileage: 0
Licence:

Invoice #:
Date In: 22 APR 24
Promised: 30 APR 24
Date Sched:
Completed: 12 JUN 24
Warr. Date: 30 APR 24

Job #FPDINTT - Internal

Transferred to BAS*73551 on 02 MAY 24
Estimate amount was 0.00
FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

Transferred to BAS*73551 on 02 MAY 24
Estimate amount was 0.00
10K E2 EQUALIZER HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #E2: 0.00

Job #BCWV - Internal

Transferred to BAS*73551 on 02 MAY 24
Estimate amount was 0.00
BRAKE CONTROL & WIRING - VAN, SUV & CAR

Labor

Code	Description	Mechanic	Total
BCWV	BRAKE CONTROL & WIRING - VAN, SUV &	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BCWV: 0.00

Job #DELUXE - Internal

Transferred to BAS*73551 on 02 MAY 24
Estimate amount was 0.00
DELUXE STARTER KIT



Customer #: 54410
GURDO, JR, ARTHUR
SAMUEL



Subtotal for Job #DELUXE: 0.00

Job #1 - Internal

COMPLAINT: Transferred to BAS*73551 on 02 MAY 24

Estimate amount was 0.00

WONKY TRIM ABOVE BED NEAR THE COAX CEILING/WALL

CAUSE: WONKY TRIM ABOVE BED NEAR THE COAX CEILING/WALL

CORRECTION: This is the vinyl trim tha covers any gap between the ceiling and the wall. It does not shrink on an inside corner and leaves a gap. This is common.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: Transferred to BAS*73551 on 02 MAY 24

Estimate amount was 0.00

LOOK AT THE SLIDE ROOM ON THE RIGHT SIDE THE TOP LIP YOU CAN SEE WOOD AT THE TOP

CAUSE: LOOK AT THE SLIDE ROOM ON THE RIGHT SIDE THE TOP LIP YOU CAN SEE WOOD AT THE TOP

CORRECTION: Looked at area in question on back of top slideout flange. (Front). This area is on the inside of camper and is not subjected to the outside weather. The vinyl is too short to cover the spot. Trying to stretch the vinyl and secure it will cause it to tear.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: PULL OUT BEHIND THE COUCH THERE IS SOMTHING STICKY ON IT VINYL COMING LOOSE ON DINETTE AND CHIP IN WOOD OVER SOFA

CAUSE: PULL OUT BEHIND THE COUCH THERE IS SOMETHING STICKY ON IT

CORRECTION: Excess glue on edge of bunk pullout. Used mineral spirits and alcohol to remove glue from leather trim on pullout bunk.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Subtotal for Job #3: 85.00

Job #4 - Warranty

COMPLAINT: BATHROOM SINK LEAKS

CAUSE: BATHROOM SINK DRAIN LEAKS

CORRECTION: Bathroom shower corner sink drain installed crossed threaded. Removed drain pipes and straightened fittings. Remounted drain "P" trap straight. Checked for leaks. No leaks at this time.



W/O: 73447
Promised Date: 30 APR 24



Customer #: 54410
GURDO, JR, ARTHUR
SAMUEL



W/O: 73447
Promised Date: 30 APR 24



Customer #: 54410
GURDO, JR, ARTHUR
SAMUEL



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	85.00
Subtotal for Job #4:			85.00

Job #MONSTER - Internal

COMPLAINT: Transferred to BAS*73551 on 02 MAY 24
Estimate amount was 0.00
MONSTER SEAL IN ALL TIRES

CAUSE: DH DID AT LUNCH AND SHAWN AIRED UP TIRES.

CORRECTION: INSTALL MONSTER SEAL IN BOTH TIRES

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #MONSTER:			0.00

Job #4EVERBATT - Internal

COMPLAINT: Transferred to BAS*73551 on 02 MAY 24
Estimate amount was 0.00
"FOREVER START" BATTERY PROTECTION
LIFETIME WARRANTY - ORIGINAL OWNER ONLY

CORRECTION: DH TOOK PICTURES AND SENT TO BEN. SPRAY BATTERY.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #4EVERBATT:			0.00

Job #5 - Internal

PARTS ONLY CUSTOMER WANTED PARTS
REPLACED FOREST RIVER SAID REPAIR

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Parts				
Part #	Description	Qty	Price	Total
F100374060	FABRIC BUTTON, #30 SNAP W/ELLIOT GRO	12.00	N/C	N/C
F100328893	BATTEN, 1" X 8' - MIMOSA MAPLE (SET	1.00	N/C	N/C
F100214258	FABRIC, BOGEY IRON 54" WIDE (SOLD BY	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-TACKS AND BATTEN	1.00	N/C	N/C
FRT	UPS-FABRIC	1.00	N/C	N/C

Subtotal for Job #5: 0.00



W/O: 73447
Promised Date: 30 APR 24

Parts Total:	0.00
Labour Total:	170.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	170.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Jun 2024



Customer #: 54410
GURDO, JR, ARTHUR
SAMUEL

