

**Pre-Authorization**

Pre-Authorization number PA03659830 Reference no: 73449 Status: Approved Approved by papca Approved date 5/3/2024  
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTCGM22RV50622E  
 600 E Baseline Rd  
 Evansville, IN 47725

Nu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
mbe	operation								
r of									
1	1207514A	Step - Repair	0.00	0.40	0.30		1	0.50	Complaint:THE LATCH THAT HOLDS THE STEPS UP ON THE LEFT SIDE DOES NOT LATCH Cause:Entry steps won't latch in the up position Correction:Tighten loose bolts, adjust linkage, adjust latch, lube latch. Operates properly now. KRV – REPAIR ONLY approved.
2	6200206B	LP Bottle - Replac	0.00	0.30	0.20		1	0.20	Complaint:ONE OF THE LP TANKS WILL NOT FILL Cause:LP tank will not fill Correction:Try and get tank to fill, had Ben try to no luck. Replace tank and fill it. KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item.
3	6101024B	Drain Valves with	0.00	0.10	0.10		1	0.10	Complaint:DUMP VALVE MISSING HANDLE Cause:MISSING HANDLE Correction:INSTALL HANDLE KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
4	5101214A	Coax, TV - Repair	0.00	0.70	0.30		1	0.30	Complaint:NO TV CHANNELS Cause:TV antenna is not working Correction:Strip wire on the end of coaxial cable in the distribution box at rear of trailer. KRV – REPAIR ONLY approved.
					0.90				

Pre-Authorization number PA03659830

For paper claims only use one pre-authorization number per warranty claim for  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company