



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73449  
Promised Date:  
24 MAY 24

### CUSTOMER WORK ORDER

WO #: 73449

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: PH  
Location: 0501 BH TO CLOSE

Stock #: 11364  
Stock Desc: 2024 TT KEYSTONE  
COUGAR HALF-TON 25MLE  
Chassis #: 4YDTCGM22RV506225  
Serial #: 4YDTCGM22RV506225  
Mileage: 0  
Licence:

Invoice #:  
Date In: 22 APR 24  
Promised: 31 MAY 24  
Date Sched:  
Completed: 30 APR 24  
Warr. Date:



Customer #: 1000  
BASDEN'S AMERICAN RV,



#### Job #PDINTT - Internal PDI - NEW TRAVEL TRAILER

##### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

##### Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

##### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #1 - Warranty

COMPLAINT: THE LATCH THAT HOLDS THE STEPS UP ON THE LEFT SIDE DOES NOT LATCH

CAUSE: Entry steps won't latch in the up position

CORRECTION: Tighten loose bolts, adjust linkage, adjust latch, lube latch. Operates properly now.

##### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	51.00

**Subtotal for Job #1: 51.00**

#### Job #2 - Warranty

COMPLAINT: ONE OF THE LP TANKS WILL NOT FILL

CAUSE: LP tank will not fill

CORRECTION: Try and get tank to fill, had Ben try to no luck. Replace tank and fill it.

##### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00



W/O: 73449  
Promised Date: 31 MAY 24



Customer #: 1000  
BASDEN'S AMERICAN RV,



**Parts**

Part #	Description	Qty	Price	Total
66-4907	L.P.CYLINDER 30 LB. PW	1.00	80.50	80.50

**Subtotal for Job #2: 114.50**

**Job #3 - Warranty**

DUMP VALVE MISSING HANDLE

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	2.00

**Parts**

Part #	Description	Qty	Price	Total
11-0630	GRENTEC EXT. ROD KIT	1.00	12.68	12.68

**Subtotal for Job #3: 14.68**

**Job #4 - Warranty**

COMPLAINT: NO TV CHANNELS

CAUSE: TV antenna is not working

CORRECTION: Strip wire on the end of coaxial cable in the distribution box at rear of trailer.

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	51.00
Z990	MISCELLANEOUS REPAIR	JH	0.00

**Subtotal for Job #4: 51.00**

Parts Total:	93.18
Labour Total:	138.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>231.18</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 03 May 2024

