

Pre-Authorization

Pre-Authorization number PA03670442 Reference no: 73476 Status: Approved Approved by steic Approved date 5/22/2024

Servicing Dealer Name Address VIN Retail sold on

1194 Basden's American RV Basden's American RV 4YDTSGL23R7104318 5/20/2024
600 E Baseline Rd
Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1102716B	Center Cap	0.00	0.20	0.20		1	0.20	Complaint:THE GREASE CAP ON THE ROADSIDE FRONT AXLE IS COMING OFF. Cause:GREASE CAP ON THE ROADSIDE FRONT AXLE IS COMING OFF Correction:Removed tire and wheel from axle. Put grease cap back on axle. Remounted tire and wheel. Torqued lug nuts.
2	6104015A	Shower/Tub - Wal	0.00	0.20	0.20		1	0.50	Complaint:SHOWER SURROUND NEEDS RESEALING AT TOP Cause:SHOWER SURROUND NEEDS RESEALING AT TOP (NOTED AT DELIVERY) Correction:Resealed Shower surround at top with clear silicone
					<u>0.40</u>				

Pre-Authorization number PA03670442

For paper claims only use one pre-authorization number per warranty claim for
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company