

BASDEN RV CENTER, INC dba AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 US  
 47725  
 812-867-5200

WARRANTY CLAIM # 73499  
 MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
 Customer: 3855 - TODD G. McCONNELL  
 Address: 2394 E 350 S PRINCETON, IN

47670

Phone: 812-385-6823

Stock Number: 11279 - 2024 COUGAR 316RLSSE 4YDFCGR20R2502343

VIN: 4YDFCGR20R2502343 HIN: SER#: 4YDFCGR20R2502343

Mileage: 0 Work Order Comp: 10 JUN 24

Auth. No: Dealer #: 1194

Warr. Date: 19 APR 24 Work Order Date: 26 APR 24 Inv #: 405573

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
73499	1	WHEN THE CUSTOMER CAME TO PICK UNIT UP HE FOUND A CUT IN THE ROOF AND FOUND THE THE ROOF HAS BEEN SOFT AND IS NOW BUBBLY IN THE AREA THAT IT IS Roof Remove both aircons. Remove 2 pipe vents. Remove 2 vents and max air covers. Remove antenna. Remove skylight. Remove 2 attic vents. Remove gutters on both sides. Remove front and rear trim. Remove old rubber roofing. Took a pick of area that got wet. Glue and staple down 1/4" underlayment. Cut out vent holes. Sand down seams. Put seam tape on. Put tape on edges.	

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
520357	1	1/4" UNDERLAYMENT		10.00	36.03	360.30
376374	1	Adhesive - Roof - 8010 - 1 Gal/Ca		2.00	64.31	128.62
639155	1	Sealant - Self Leveling - 5121 Al		14.00	11.17	156.38
639157	1	Sealant - Lap Caulk - 5160 White		4.00	16.41	65.64
679920	1	Roof - Membrane - 9.5' x 45' - Al		1.00	442.95	442.95
4582	1	FLAT TRANSITION TRIM BLACK OR WHI		1.00	12.06	12.06
338110	1	Trim - Corner Insert - T-4 Long L		1.00	13.11	13.11
500627	1	CLEAR SIKASIL PLUS		1.00	18.22	18.22
3388	1	551LSB-1 BLACK NON SAG DICOR		1.00	7.69	7.69
PUTTY	1	PUTTY TAPE - ROLL		2.00	7.22	14.44

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISCELLANEOUS REPAIR		6.80	170.00	1156.00

Claim : 73499

```
*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      1  MISCELLANEOUS REPAIR          2.60    170.00    442.00
Z990      1  MISCELLANEOUS REPAIR          4.00    170.00    680.00
Z990      1  MISCELLANEOUS REPAIR          6.84    170.00   1162.80
Z990      1  MISCELLANEOUS REPAIR          0.24    170.00     40.80
Z990      1  MISCELLANEOUS REPAIR          9.08    170.00   1543.60
Z990      1  MISCELLANEOUS REPAIR          1.10    170.00    187.00
Z990      1  MISCELLANEOUS REPAIR          2.86    170.00    486.20
Z990      1  MISCELLANEOUS REPAIR          3.14    170.00    533.80
Z990      1  MISCELLANEOUS REPAIR          0.45    170.00     76.50
Z990      1  MISCELLANEOUS REPAIR          0.32    170.00     54.40
Z990      1  MISCELLANEOUS REPAIR          0.18    170.00     30.60
Z990      1  MISCELLANEOUS REPAIR          0.16    170.00     27.20
Z990      1  MISCELLANEOUS REPAIR          0.43    170.00     73.10
*****
```

```
*****
Excode    Job#  Description          EXTRAS          Qty      Price     Total
*****
FRT        1  UPS-SEALANTS          1.00     41.02     41.02
FRT        1  FREIGHT-MEMBRANE      1.00    149.78    149.78
*****
```

Parts Total: 1,219.41  
Labour Total: 6,494.00  
Sublet Total: 0.00  
Extras Total: 190.80

>>>> Claim Total: 7,904.21

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_