



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73500
Promised Date:
24 MAY 24



Customer #: 2212
SCHILLING, THOMAS



CUSTOMER WORK ORDER

WO #: 73500 (Appointment Date: 27 APR 2024 - Time: 10:00am)

Customer: 2212 - SCHILLING, THOMAS
- 812-631-1250

Tag: BH - SCREEN CLIPS ORDERED.
5-3-24

Author: BH

Location: 0510 BH TO CLOSE

Stock #: 11303

Stock Desc: 2024 TT KEYSTONE

SPRINGDALE 1700FQ

Chassis #: 4YDTSGG10RW101562

Serial #: 4YDTSGG10RW101562

Mileage: 0

Licence:

Invoice #:

Date In: 27 APR 24

Promised: 31 MAY 24

Date Sched:

Completed: 10 MAY 24

Warr. Date: 06 APR 24

Job #1 - Warranty

COMPLAINT: ON THE GREY WATER TANK DRAIN HAS A LEAK

CAUSE: Filled grey tank. Hose clamp was loose. Tightened clamp.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR DOES NOT WANT TO CLOSE RIGHT

CAUSE: Bottom of the door is bowed inward. Pulled door so it isn't hitting frame.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: THE SCREEN FELL OUT OF THE EGRESS WINDOW

CAUSE: Installed screen. Missing one of the screen holders

CORRECTION: installed screen holder

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



350861 Window - Screen Clip - Black - Cleer 1.00 0.53 0.53

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-CLIP	1.00	17.89	17.89

Subtotal for Job #3: 35.42

Job #4 - Warranty

COMPLAINT: THE FRONT COMPARTMENT DOOR ON THE DOOR SIDE WAS WET AFTER A RAIN STORM IT WAS THE CUSTOMERS FIRST TRIP

CAUSE: Seal on door is compressed. Put a slightly larger seal on door.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	51.00

Parts

Part #	Description	Qty	Price	Total
311450	Seal - D Seal - EPDM - .57" x .44"	5.00	0.22	1.10

Subtotal for Job #4: 52.10

Parts Total: 1.63
Labour Total: 136.00
Sublet Total: 0.00
Extras Total: 17.89

WORK ORDER TOTAL: 155.52

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 May 2024

W/O: 73500
Promised Date: 31 MAY 24



Customer #: 2212
SCHILLING, THOMAS

