

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 73507
 MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
 Customer: 1000 - BASDEN'S AMERICAN RV
 Address: 600 E. BASELINE RD. EVANSVILLE, IN
 USA
 47725

Phone:

Stock Number: 11270 - 2024 SPRINGDALE 200RLC 4YDTSGJ29R7100132
 VIN: 4YDTSGJ29R7100132 HIN: SER#: 4YDTSGJ29R7100132
 Mileage: 0 Work Order Comp: 30 APR 24
 Auth. No: Dealer #: 1194
 Warr. Date: 27 APR 24 Work Order Date: 27 APR 24 Inv #: 404035

WO #	Job #	Description	JOB INFORMATION
73507	1	THE BIG REAR WINDOW IS HARD TO OPEN AND THE BOTTOM OF THE WINDOW IS BOWED THE BIG REAR WINDOW IS HARD TO OPEN AND THE BOTTOM OF THE WINDOW IS BOWED Removed window mounting screws across bottom of window. Screws across bottom were put in at an angle causing mounting frame to be bowed up. Reattached mounting ring with new screws inserted straight in to eliminate frame being bowed up.	
73507	2	ON THE BOTTOM OF THE BIG REAR WINDOW THE PAPER IS PEALING OFF NEED TO GLUE IT DOWN TO MAKE SURE IT DOES NOT GET WORST ON THE BOTTOM OF THE BIG REAR WINDOW THE PAPER IS PEALING OFF NEED TO GLUE IT DOWN TO MAKE SURE IT DOES NOT GET WORST Straightened wall paper and applied glue to hold area in place. Taped temp with blue tape. Removed tape after glue was dry.	

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISCELLANEOUS REPAIR		0.20	170.00	34.00
Z990	1	MISCELLANEOUS REPAIR		0.00	170.00	0.00
Z990	2	MISCELLANEOUS REPAIR		0.00	170.00	0.00
Z990	2	MISCELLANEOUS REPAIR		0.10	170.00	17.00

Parts Total: 0.00
 Labour Total: 51.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 51.00

Customer Signature: _____

Date: _____