

e-Authorization

5/6/20
04:52:40 p

3-Authorization number PA03660606 Reference no: 73507 Status: Approved Approved by anglr Approved date 5/6/2024
 Pricing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSJ29R7100132
 600 E Baseline Rd
 Evansville, IN 47725

Item	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2315814A	Window - 48" or l	0.00	0.80	0.20		1	0.20	Complaint:THE BIG REAR WINDOW IS HARD TO OPEN AND THE BOTTOM OF THE WINDOW IS BOWED Cause:THE BIG REAR WINDOW IS HARD TO OPEN AND THE BOTTOM OF THE WINDOW IS BOWED Correction:Removed window mounting screws across bottom of window. Screws across bottom were put in at an angle causing mounting frame to be bowed up. Reattached mounting ring with new screws inserted straight in to eliminate frame being bowed up.
2	3201616B	Batten Tape - Ref	0.00	0.10	0.10		1	0.20	Complaint:ON THE BOTTOM OF THE BIG REAR WINDOW THE PAPER IS PEALING OFF NEED TO GLUE IT DOWN TO MAKE SURE IT DOES NOT GET WORST Cause:ON THE BOTTOM OF THE BIG REAR WINDOW THE PAPER IS PEALING OFF NEED TO GLUE IT DOWN TO MAKE SURE IT DOES NOT GET WORST Correction:Straithtened wall paper and applied glue to hold area in place. Taped temp with blue tape. Removed tape after glue was dry.

3-Authorization number PA03660606 0.30

paper claims only use one pre-authorization number per warranty claim for
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the