



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73525



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 73525

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0520 CHECK PREAUTH

Stock #: 11385

Stock Desc: 2024 TT ALLIANCE RV
DELTA 292RL

Chassis #: 7M5TD3320RC303450

Serial #: 7M5TD3320RC303450

Mileage: 0

Licence:

Invoice #:

Date In: 30 APR 24

Promised:

Date Sched:

Completed: 17 MAY 24

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI new trailer

CORRECTION: PDI new trailer

Checked

Water and plumbing systems

Electrical system

12vdc system

LP system, passed leak test

Interior and exterior

Lights

Running gear

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: KITCHEN SINK DOES NOT DRAIN

CAUSE: Kitchen sink doesn't drain

CORRECTION: Sink wouldn't drain, found a switch to garbage disposal that wasn't in plain sight.
Used label maker to make labels to mark switch for customer reference. No problems with drain found after locating switch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C



Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: RIGHT SIDE BELLY HOT + COLD SHOWER LOST COVER

CAUSE: Right side belly hot and cold shower cover was off of port.

CORRECTION: Reinstall cover

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ALL HOT AND COLD SHOWER VALVE PORTS ARE STUCK AND WON'T ACCEPT HOSE FITTING FOR THE HOSE

CAUSE: Hot and old shower valves wouldn't accept nipple to accept hose.

CORRECTION: Used a punch to free up valves, all valves now accept hose nipple for outdoor showers.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	17.00

Subtotal for Job #3: 17.00

Parts Total:	0.00
Labour Total:	17.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	17.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 May 2024

W/O: 73525



Customer #: 1000
BASDEN'S AMERICAN RV,

