

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73540
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV
Customer: 54739 - DECKER PETROLEUM INC
Address: 10870 S US HWY 41 DECKER, IN

47524

Phone: 812-664-4153

Stock Number: 11232 - 2023 RETRO 210 59CCC2329PL006450

VIN: 59CCC2329PL006450 HIN:

SER#: 59CCC2329PL006450

Mileage: 0

Work Order Comp: 31 MAY 24

Auth. No:

Dealer #:

Warr. Date: 03 MAY 24

Work Order Date: 01 MAY 24

Inv #: 405468

WO # Job # Description JOB INFORMATION

73540 1 UNDERBELLY HANGING DOWN IN 2 PLACES
UNDERBELLY HANGING DOWN IN (2) PLACES AND ACROSS REAR OF UNIT
All old tape securing cuts in underbelly is peeling off. Reoved
all remaining tape. Secured underbelly cuts with wood strips to
hold ion place. Cleaned all surfaces so that new underbelly tape
can be applied. Retaped all areas, across rear of unit and two
areas around plumbing access.

73540 2 WATER LEAKING OUT OF CITY WATER CONNECTION
WATER LEAKING OUT OF CITY WATER CONNECTION.
Water leaks out of city water connection when water pump is
turned on. Removed complete water housing from unit.
Disassembled city water connection. The O Ring has come off of
the check valve. Remounted O Ring. Reassembled city water
connection. Remounted complete water housing unit. Checked for
leaks. Resealed around housing with clear silicone.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 1.50 168.00 252.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 168.00 50.40

Parts Total: 0.00
Labour Total: 302.40
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 302.40

Customer Signature: _____

Date: _____

Claim : 73540

```
*****
Lab Code  Job#  Description      LABOUR                      Hrs      Rate      Total
*****
```