

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
<b>BASDEN RV CENTER INC</b>		<b>CLAIM</b>	1924856
<b>DBA AMERICAN RV CENTER</b>		<b>CLAIM ORIGIN</b>	WEB
<b>600 E BASELINE ROAD</b>		<b>ORIGINAL CLAIM ID</b>	
<b>EVANSVILLE, IN 47725</b>		<b>VIN</b>	5ZT2CXHC6RL016916
<b>USA</b>		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$170.00	<b>SITE/WAREHOUSE</b>	224 / 224
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	AAPT187RB
<b>CARLOS C WITTE III</b>		<b>DEALER RO #</b>	73638
<b>605 S FOXTROT COURT</b>		<b>CLAIM START DATE</b>	05/21/2024
<b>Huntingburg, IN 47542</b>		<b>CLAIM END DATE</b>	01/01/1900
<b>USA</b>			
<b>Retail Date of Purchase</b>	05/20/2024	<b>WARRANTY EXPIRATION DATE</b>	05/20/2025

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	60-136-01-00-001480	City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-05-21 12:07:21 :: CITY WATER CONNECTION LEAKS CITY WATER CONNECTION LEAKS When running water pump, water leaks out of city water connection. Removed city water connection from side of unit. Cleaned off old sealer around flange. Applied putty tape to back of flange. Turned on water pump and checked for leaks. No leaks. Mounted city water connection.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b>	\$51.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b>	\$51.00
	<b>Notes</b>			

<b>Submitted</b>	<b>Labor Amt</b>	\$51.00	<b>Approved</b>	<b>Labor Amt</b>	\$51.00
	<b>Parts &amp; Freight</b>	\$0.00		<b>Parts &amp; Freight</b>	\$0.00
	<b>Total</b>	\$51.00		<b>Total</b>	\$51.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
All repairs described have been inspected and are satisfactory.