

e-Authorization

6/4/20
05:01:19 PM

Pre-Authorization number PA03675345 Reference no: 73656 Status: Approved Approved by angle Retail sold on Approved date 5/30/2024

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGM24R7105055					
Job Root or operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1 2300114F	Entrance Door - I	0.00	0.20	0.40		2	0.20	Complaint:ENTRY DOOR WONT LATCH AT ALL Cause:Front entry door won't latch at all Correction:Adjust door catch to allow door to latch properly
2 2300514A	Entrance Door - I	0.00	0.20			1	0.20	Complaint:Adjust door catch to allow door to latch properly Cause:Rear entry door needs adjusted Correction:Adjust catch so door will latch properly
3 3100814F	Cabinet Door - Ad	0.00	0.20	0.10		1	0.10	KRV - moved to line 1 Complaint:PANTRY DOOR WONT LATCH Cause:Pantry door won't close Correction:Remove catch and move it up a 1/4 inch to get the latch to contact it properly.
4 3200814A	Door - Interior Slic	0.00	0.20	0.20		1	0.20	KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual Complaint:BATHROOM DOOR DOSENT WANT TO OPEN Cause:Bathroom door hard to get open Correction:Adjust door catch to allow door to open properly
5 6104115A	Shower/Tub - Bas	0.00	0.30	0.30		1	0.50	Complaint:SHOWER SURROUND NEEDS SEALED AT THE TOP Cause:Shower surround needs sealed Correction:Sealed areas at the top of surround that needed sealant
Pre-Authorization number PA03675345				1.00				

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the