



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73656
Promised Date:
24 MAY 24

CUSTOMER WORK ORDER

WO #: 73656

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0531 BH TO CLOSE

Stock #: 11391
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 261BHC
Chassis #: 4YDTSGM24R7105055
Serial #: 4YDTSGM24R7105055
Mileage: 0
Licence:

Invoice #:
Date In: 13 MAY 24
Promised: 31 MAY 24
Date Sched:
Completed: 31 MAY 24
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 4 HR PDI

CAUSE: PDI new trailer

CORRECTION: Checked
Water and plumbing systems
Electrical system
12vdc system LP system, passed leak test
Interior and exterior
Lights
Running gear

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR WONT LATCH AT ALL

CAUSE: Front entry door won't latch at all

CORRECTION: Adjust door catch to allow door to latch properly

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00
Z990	MISCELLANEOUS REPAIR	JH	0.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: REAR ENTRY DOOR NEEDS ADJUSTED

CAUSE: Rear entry door needs adjusted

CORRECTION: Adjust catch so door will latch properly

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00
Z990	MISCELLANEOUS REPAIR	JH	0.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: PANTRY DOOR WONT LATCH

CAUSE: Pantry door won't close

CORRECTION: Remove catch and move it up a 1/4 inch to get the latch to contact it properly.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: BATHROOM DOOR DOESNT WANT TO OPEN

CAUSE: Bathroom door hard to get open

CORRECTION: Adjust door catch to allow door to open properly

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00

Subtotal for Job #4: 34.00

Job #5 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED AT THE TOP

CAUSE: Shower surround needs sealed

CORRECTION: Sealed area's at the top of surround that needed sealing.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	51.00

Subtotal for Job #5: 51.00

Parts Total: 0.00
 Labour Total: 170.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 170.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Jun 2024

W/O: 73656
Promised Date: 31 MAY 24



Customer #: 1000
BASDEN'S AMERICAN RV,

