



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73735



Customer #: 53904
GRAY, ANGELA K.



CUSTOMER WORK ORDER

WO #: 73735 (Appointment Date: 21 MAY 2024 - Time: 01:30pm)

Customer: 53904 - GRAY, ANGELA K. -
812-698-9545

Tag:

Author: PH

Location: 0531 CHECK PREAUTH

Stock #: 11129

Stock Desc: (11129) 2024 COACHMEN
CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC9RK006310

Serial #: 5ZT2CAEC9RK006310

Mileage:

Licence:

Invoice #:

Date In: 21 MAY 24

Promised:

Date Sched:

Completed: 30 MAY 24

Warr. Date: 14 AUG 23

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE TAILLAMP LENSES ARE BOTH LOOSE AND NOT SEALED.

CAUSE: taillamp lens

CORRECTION: took off lens and put in more screws in base it was coming away from metal, then put lens back on and resealed lights.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT EVEN WHEN THE GRAY TANK IS FULL, THE LEVEL INDICATOR SHOWS THAT IT IS EMPTY.

CAUSE: grey tank will not read

CORRECTION: filled tank up with water and it doesn't read, I ran wire to sensor to ground and it read full, traced ground wire crimped end and found wire was crimped but it was on coating not bare wire, so I cut it out and stripped back wires and connected together and now it shows full, let out water and it goes down by each light to empty, tied up wires, all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	170.00

Subtotal for Job #3: 170.00

Job #4 - Warranty

COMPLAINT: CITY WATER INLET CHECK VALVE IS BAD. SHOOTS WATER OUT WHEN RUNNING ON THE PUMP

CAUSE: city inlet

CORRECTION: checked inlet and O-ring is blown out the back and won't seal, installed new inlet that is brass instead of plastic, all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	51.00

Parts



Part #	Description	Qty	Price	Total
10-1105	62165 PW METAL MPT CITY WATER FLANGE	1.00	17.89	17.89

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #4: 68.89**Job #51-1722 - Warranty**

COMPLAINT: SOLAR PANEL INLET RECALL

CAUSE: solar inlet recall

CORRECTION: checked solar inlet and it is not cracked,all good ,took pictures.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00

Subtotal for Job #51-1722: 85.00**Job #24V254 - Warranty**

COMPLAINT: CHARGE LINE OVER CURRENT PROTECTION

CAUSE: charge line recall

CORRECTION: checked wires and they were wrong,reinstalled wires like they should of been and took before and after pictures,tested wires and they are good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

Subtotal for Job #24V254: 34.00

Parts Total: 17.89
Labour Total: 374.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 391.89

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 May 2024

Customer #: 53904
GRAY, ANGELA K.