

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73755
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 53800 - AMY R. BLACKORBY
Address: 9200 E CR 2000 N FERDINAND, IN

47532

Phone: 812-827-0214

Stock Number: 11259 - 2023 CATALINA SUMMIT SERIES 184BHS 5ZT2CAGC6PK005593
VIN: 5ZT2CAGC6PK005593 HIN: SER#: 5ZT2CAGC6PK005593

Mileage: 0

Work Order Comp: 31 MAY 24

Auth. No:

Dealer #:

Warr. Date: 29 JUN 23

Work Order Date: 24 MAY 24

Inv #: 405460

WO # Job # Description JOB INFORMATION

73755 1 WATER LEAK AT THE INTERIOR RIGHT INSIDE ENTRY DOOR. THE LIGHT
LENS CAP RIGHT INSIDE THE ENTRY DOOR IS FILLING UP WITH WATER.
CUSTOMER DID STATE THAT HIS SOLAR INLET WAS MISSING A CAP.
water leaking in interior light
got on roof and found solar inlet was broke across back side, took
out screws and cut inlet out of rubberized coating, and trimmed
back rubber coating, checked in hole for wetness and it was
damp, but nothing was hurt, installed new solar inlet and sealed
with dicor and wired up, took light down inside and cleaned lens
and checked inside ceiling and it is dry all good.

Part No Job# Description PARTS Qty Price Total

DCR505LSW-1 1 PW HAPS FREE SELF-LEVELING DICOR 1.00 7.31 7.31

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 170.00 85.00

Parts Total: 7.31
Labour Total: 85.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 92.31

Customer Signature: _____

Date: _____

