

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1933731
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAGC6PK005593
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT184BHS
AMY R BLACKORBY		DEALER RO #	73755
9200 E CR 2000 N		CLAIM START DATE	05/29/2024
Ferdinand, IN 47532		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	07/01/2023	WARRANTY EXPIRATION DATE	07/01/2024

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	40-124-01-11-002631	Exterior Solar Panel Port or Inlet - Electrical/Solar Power/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-05-29 15:11:43 :: WATER LEAK AT THE INTERIOR RIGHT INSIDE ENTRY DOOR. THE LIGHT LENS CAP RIGHT INSIDE THE ENTRY DOOR IS FILLING UP WITH WATER. CUSTOMER DID STATE THAT HIS SOLAR INLET WAS MISSING A CAP. water leaking in interior light got on roof and found solar inlet was broke across back side, took out screws and cut inlet out of rubberized coating, and trimmed back rubber coating, checked in hole for wetness and it was damp ,but nothing was hurt, installed new solar inlet and sealed with dicor and wired up, took light down inside and cleaned lens and checked inside ceiling and it is dry all good.			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$85.00
	Serial#	Appr Hrs	0.50	Appr Labor Amt \$85.00
	Notes			
	AUTHORIZED AS REQUESTED			

Submitted	Labor Amt	\$85.00	Approved	Labor Amt	\$85.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$85.00		Total	\$85.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.