



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73755
Promised Date:
24 JUN 24



CUSTOMER WORK ORDER

WO #: 73755 (Appointment Date: 24 MAY 2024 - Time: 10:00am)

Customer: 53800 - BLACKORBY, AMY R. Stock #: 11259

- 812-827-0214

Tag: PH - ROOF PLATE ORDERED.

Author: PH

Location: 0607 BH TO CLOSE

Stock Desc: 2023 TT COACHMEN

CATALINA SUMMIT SERIES 184BHS

Chassis #: 5ZT2CAGC6PK005593

Serial #: 5ZT2CAGC6PK005593

Mileage: 0

Licence:

Invoice #:

Date In: 24 MAY 24

Promised: 29 JUN 24

Date Sched:

Completed: 31 MAY 24

Warr. Date: 29 JUN 23

Job #1 - Warranty

COMPLAINT: WATER LEAK AT THE INTERIOR RIGHT INSIDE ENTRY DOOR. THE LIGHT LENS CAP RIGHT INSIDE THE ENTRY DOOR IS FILLING UP WITH WATER. CUSTOMER DID STATE THAT HIS SOLAR INLET WAS MISSING A CAP.

CAUSE: water leaking in interior light

CORRECTION: got on roof and found solar inlet was broke across back side, took out screws and cut inlet out of rubberized coating, and trimed back rubber coating, checked in hole for wetness and it was damp, but nothing was hurt, installed new solar inlet and sealed with dicor and wired up, took light down inside and cleaned lens and checked inside ceiling and it is dry all good.

Customer #: 53800
BLACKORBY, AMY R.



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	7.31	7.31

Subtotal for Job #1: 92.31

Parts Total: 7.31
Labour Total: 85.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 92.31

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 Jun 2024

