

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1933668
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAMB6PU041011
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT231MKS-8
DYLAN C SCHMITT		DEALER RO #	73769
2023 BULLDOG LN		CLAIM START DATE	05/29/2024
Evansville, IN 47714		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	07/01/2023	WARRANTY EXPIRATION DATE	07/01/2024

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-102-01-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code		
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2024-05-29 14:48:13 :: WALL PAPER IS PEALING IS BUBBLING AND DOING LIKE THE OTHER PANELS AS THE LAST TIME IT WAS IT IN THE LIVING ROOM OFF DOOR SIDE Wall board Went through the whole trailer. Took pics. Heated up areas that were lose. And putty holes.		
Model#	Dlr Sub Hrs	1.50	Sub Labor Amt	\$255.00
Serial#	Appr Hrs	1.50	Appr Labor Amt	\$255.00
	Notes	PLEASE DO A COMPLETE WALK THROUGH THE ENTIRE UNIT FOR ANY OTHER EFFECTED PANELING. We did and found those spots PENDING VENDOR REVIEW AUTHORIZED PER VENDOR VCB PATRICK IND PER SCOTT WARREN		

Submitted	Labor Amt	\$255.00	Approved	Labor Amt	\$255.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$255.00		Total	\$255.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.