



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73797
Promised Date:
06 JUN 24

CUSTOMER WORK ORDER

WO #: 73797

Customer: 54845 - BRODE, LISA -
941-400-0720

Tag:

Author: BH

Location: 0620 BH TO CHECK STATUS
WOTH RIVERSIDE

Stock #: 11233

Stock Desc: 2023 TT RIVERSIDE RV
RETRO 210

Chassis #: 59CCC2322PL006449

Serial #: 59CCC2322PL006449

Mileage:

Licence:

Invoice #:

Date In: 29 MAY 24

Promised: 06 JUN 24

Date Sched:

Completed: 20 JUN 24

Warr. Date: 06 JUN 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: final pdi

CORRECTION: did final and everything on sheet and also checked water,lp,electrical,and appliances.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
40549	40549 BLACK LP TANK COVER LID - CAMCO	1.00	N/C	N/C
55-8173	CIRCUIT BREAKER-40A	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: monster seal

CORRECTION: jacked up all four tires and let out air and put in monster seal and aired back up.and put on all 4 stickers.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Customer #: 54845
BRODE, LISA



Subtotal for Job #MONSTER: 0.00

Job #E26K - Internal

COMPLAINT: E2 6K HITCH INSTALLED

CAUSE: e2 hitch

CORRECTION: installed brackets on camper and put hitch head together. Assembled hitch brackets and mounted on frame of unit. Removed broken circuit braker and install new braker. SEt hitch height on tow vehicle.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
21200	21200 REDUCER BUSHING 1 1/4 IN TO 1 IN YELLOW ZINC BULK	1.00	N/C	N/C
40075	2 5/16" X 1 X 3" BALL	1.00	N/C	N/C
92-00-0600	E2 TRUNNION HITCH 6000# 2-POINT WITH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #E26K: 0.00

Job #1 - Internal

WASHBAY MAXX GAURD

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: COLD SIDE NOT WORKING ON PUMP, HAS KINK SOMEWHERE IN LINE.

CAUSE: cold side line had crimp in it not getting water to pump

CORRECTION: marked kink with zip tie and took pic,cut line off and installed a longer one so it would not crimp again.hard to get to due to tight space.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	80.00

Parts

Part #	Description	Qty	Price	Total
C01292790	1/2" BLUE PVC HIGH PRESSURE HOSE	3.00	0.24	0.72

Subtotal for Job #2: 80.72

Job #WALK - Internal

COMPLAINT: WALK THRU

CAUSE: walk thru

CORRECTION: did walk thru customer never had a camper before had lots of questions,set up hitch showed hitch work and brake control and took them through store and sold them some stuff. Estimated Amount: 180.00



W/O: 73797
Promised Date: 06 JUN 24



Customer #: 54845
BRODE, LISA



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #WALK: 0.00

Parts Total: 0.72
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 80.72

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Jun 2024

W/O: 73797
Promised Date: 06 JUN 24



Customer #: 54845
BRODE, LISA

