



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73952
Promised Date:
20 JUN 24



Customer #: 48585
CHASTEEN, MICHAEL A.



CUSTOMER WORK ORDER

WO #: 73952 (Appointment Date: 13 JUN 2024 - Time: 03:30pm)

Customer: 48585 - CHASTEEN,
MICHAEL A. - 812-568-4874

Tag:

Author: BJW

Location: 0625 CHECK STATUS WITH
JG

Stock #: 10261

Stock Desc: (10261) 2019 KEYSTONE
SPRINGDALE 202RD

Chassis #: 4YDT20228K3106619

Serial #: 4YDT20228K3106619

Mileage:

Licence:

Invoice #: 406084

Date In: 13 JUN 24

Promised: 29 JUN 24

Date Sched:

Completed: 22 JUN 24

Warr. Date: 25 APR 19

Job #TIRE - External

COMPLAINT: DISMOUNT AND MOUNT 4 TIRES

CAUSE: dismount and mount 4 tires

CORRECTION: jacked up unit and put on jack stands and removed wheels from unit then removed tires from wheels and mounted new Goodyear endurance tires then mounted wheels to unit and took unit off jack stands and toqured lugs to 110 foot pounds. tires were set to 65 psi.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
724861519	GY ENDURANCE ST205/75R15 L.R. D	4.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
TDF	TIRE DISPOSAL FEE	4.00	N/C	N/C
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #TIRE: 0.00

Job #2 - External

COMPLAINT: CUSTOMER ADVISES THAT THE CO2 DETECTOR KEEPS GOING OFF.

CAUSE: replace co2 detector

CORRECTION: removed old co2 detector and got with prs to get new one and replaced with new

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
7969	BLK UNIVERSAL LP/CO DETECTOR	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #REGULATOR - Warranty

COMPLAINT: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414
SECTION:71 COMPONENT:414 OPERATION:7141442B

CAUSE: regulator recall





CORRECTION: removed old regulator and replaced with new made sure was properly secure then preformed lp safty test when doing so it was over 90 degrees and the furnace would not kick on so i had to turn on ac unit and wait for the air in the camper to get cooler while i waited i took the range top off and disconnected line going into range and hooked up to manometer when it was cool enough i was able to turn on furnace and preform lp safty test and once dropped down to 8 W.C. and waited for 5 minutes the pressure went up to 9W.C. after the five minutes

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	85.00

Parts

Part #	Description	Qty	Price	Total
696405	RECALL REGULATOR KIT W/HOSES - KEYST	1.00	28.75	28.75

Subtotal for Job #REGULATOR: 113.75

Parts Total: 28.75
Labour Total: 85.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 113.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 Jul 2024

