

Pre-Authorization

Pre-Authorization number PA03696408 Reference no: 73971 Status: Approved Approved by stept Approved date 7/8/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDFCGR20R2502343 4/26/2024
 600 E Baseline Rd
 Evansville, IN 47725

Nu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4157106A	A/C - Furrion - Re	0.00	6.00	6.00		1	0.50	Complaint:KEYSTONE WILL APPROVE 6 HRS TO INSTALL RELOCATE THERMO TEMP Cause:Relocation per zain Correction:INSTALLED 2 TEMP SENSOR RELOCATION KITS AND TESTED SYSTEM. I RAN BOTH AIR CONDITIONERS TOGETHER AND ON THERE OWN. THE THERMOSTATS ARE NOW READING THE ROOM TEMP AT THE THERMOSTAT LOCATION AND NOT IN THE RETURN VENT. Removed corner trim by stairs. Removed trim on top of wall. Pulled panel back. In bedroom Removed corner trim. And remove top trim on wall. Pulled panel back. Stapled panels back. Nailed back both corner trim and top trim. Putty holes. KRV – Labor time adjusted allowing for proper repair procedure to be performed.

Pre-Authorization number PA03696408 6.00

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company