BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74029
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 49939 - LINDSEY L. BURGER
Address: 2223 N. MARIE CT., HUNTINGBURG, IN

47542
Phone: 812-661-0019
Stock Number: 11299 - 2024 APEX NANO 208BHS 5ZT2CXKB2RL016847
VIN: 5ZT2CXKB2RL016847 HIN: SER#: 5ZT2CXKB2RL016847
Mileage: 0 Work Order Comp: 30 JUN 24
Auth. No: Dealer #:
Warr. Date: 30 JAN 24 Work Order Date: 22 JUN 24 Inv #: 406498

WO #	Job #	Description	JOB INFORMATION
74029	1	AWNING HAS A TEAR ON THE LEFT SIDE CUSTOMER NEEDS TO PICK UP AT LEAST BY THE 2ND OF JULY.	tear on front of awning ran awning out and took pics of tag,filled out sheet to get approved through warrenty,brought camper in when new awning came in rolled out awning and tied up arms,took out screws in tube assy,pullrf of gutter spount,unhooked lights,slide out awning from gutter and unrolled fabric from tube and slide of canvas,took canvas out of box and installed on tube assy,slide canvas back in gutter rail and tube in arms and secured,untied arms and ran out and back in to line up fabric on tube and secured,slide lights in awning fabric and hooked up wires and secured,put plate over wires and resiliconed gutter spount,lights work all good.
74029	3	STRIP OF WOOD HAS COME LOOSE BY THE BATHROOM DOOR	trim strip by bathroom door is loose stapled trim back in place and covered holes.

Part No	Job#	Description	PARTS	Qty	Price	Total
V000334377	1	Solera Universal Vinyl Replacemen		1.00	217.06	217.06

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.25	170.00	212.50

Claim : 74029

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.25	170.00	42.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00

Parts Total:	217.06
Labour Total:	272.00
Sublet Total:	0.00
Extras Total:	0.00
>>>>> Claim Total:	489.06

Customer Signature:_____ Date: _____