



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74040
Promised Date:
06 JUN 24

CUSTOMER WORK ORDER

WO #: 74040

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0701 CHECK PREUTH

Stock #: 11417
Stock Desc: 2025 TT FOREST RIVER
CHEROKEE WOLF DEN 26EV
Chassis #: 4X4TCKB28SK090689
Serial #: 4X4TCKB28SK090689
Mileage: 0
Licence:

Invoice #:
Date In: 24 JUN 24
Promised: 29 JUN 24
Date Sched:
Completed: 10 JUL 24
Warr. Date: 28 JUN 24

Job #PDINTT - Internal

Transferred to BAS*74163 on 08 JUL 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER - 3 HR PDI

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: WATER HEATER DOOR HITTING FLANGE

CAUSE: Water heater door hitting flange

CORRECTION: Adjuster water heater door and flange

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00

Subtotal for Job #1: 17.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Entry door needs adjusted

CORRECTION: Adjust door catch so door closes properly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	34.00



Customer #: 1000
BASDEN'S AMERICAN RV,





Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR HITTING DOOR FRAME

CAUSE: Bathroom door hitting frame

CORRECTION: Adjust bathroom door and frame to close properly.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	34.00

Subtotal for Job #3: 34.00

Job #4 - Warranty

COMPLAINT: SILICONE AND RED STAIN ON FLOOR

CAUSE: Silicone and red stain on floor

CORRECTION: Used mineral spirits and rubbing alcohol to remove the stains on the floor

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	85.00

Subtotal for Job #4: 85.00

Job #5 - Warranty

COMPLAINT: STAPLE HOLES IN CABINESTS NEED FILLED

CAUSE: Staples holes in cabinet need filled

CORRECTION: Used fill stik to fill staple holes and blended to match cabinet

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: STAPLE HOLES IN CEILING NEED FILED

CAUSE: Staple holes in ceiling need filled

CORRECTION: Used fil stik and while putty to fill staple holes in ceiling and polished to blend in with the ceiling.

Subtotal for Job #6: 0.00

Parts Total:	0.00
Labour Total:	170.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	170.00



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Jul 2024

W/O: 74040
Promised Date: 29 JUN 24



Customer #: 1000
BASDENS AMERICAN RV,

