

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74061
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 54456 - BRYAN L. COX
Address: 2666 CONESTOGA CT NEWBURGH, IN

47630

Phone: 812-550-0714

Stock Number: 11292 - 2024 CATALINA SUMMIT SERIES 164BHX 5ZT2CAEC0RK007118
VIN: 5ZT2CAEC0RK007118 HIN: SER#: 5ZT2CAEC0RK007118
Mileage: 0 Work Order Comp: 31 JUL 24
Auth. No: Dealer #:
Warr. Date: 26 FEB 24 Work Order Date: 26 JUN 24 Inv #: 407709

WO #	Job #	Description	JOB INFORMATION
74061	1	CUSTOMER ADVISES THAT THE REFRIGERATOR BOLTS CAME LOOSE AND THE REFRIGERATOR CAME OUT OF THE REFRIGERATOR COMPARTMENT. THERE ARE 2 BRACKETS ON TOP OF THE FRIDGE. THEY HAVE BEEN PULLED OUT OF THE STILE THAT THEY SECURE TO. We will need to replace the 2 inch stile and make a bracket for mounting screws to go into. Pulled unit into shop. Removed fridge. Removed stile. Removed new stile from packaging. Cut to length. Drilled pilot holes. Took a piece of aluminum corner trim and cut to length. Drilled holes. Installed stile. Installed aluminum bracket. Drilled outhole in right bracket. Secured fridge to bracket. Cleaned up mess.	
74061	3	LEFT REAR STABILIZER IS BENT Both rear Jack's are mounted incorrectly. There are 2 L-BRACKETS mounted to the frame. Both Jack's are only secured to one of these brackets. Tech needs to removed and replace bracket and jack on drivers side. Tech will also need to properly secure the passenger side jack to both brackets.	
74061	2	BATTERY CABLE RECALL Unit fell under recall. Removed hot wire from top breaker and secured to bottom breaker.	
74061	-1722	51-1722 ROOF MOUNT SOLAR INLET (AURORA & CATALINA)	

Claim : 74061

 WO # Job # Description JOB INFORMATION

solar inlet
 took pics and inspected inlet and it is fine.

Part No	Job#	Description	PARTS	Qty	Price	Total
F100285185	1	STILE, LC 18MM" X 2" X 8'	SQUARE	1.00	6.68	6.68
2600299	3	JACK, SCISSOR BEARCLAW 24"	5000#	1.00	28.93	28.93
F100609506	3	BRACKET, JACK MOUNT 2.88 X 3.50 X		1.00	7.25	7.25

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.40	170.00	68.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.30	170.00	51.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.40	170.00	68.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.20	170.00	204.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		1.00	170.00	170.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	1722	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
SS	1	SHOP SUPPLIES		1.00	0.00	0.00
FRT	1	UPS TRIM		1.00	33.02	33.02
FRT	3	UPS-BRACKET		1.00	18.24	18.24

Parts Total: 42.86
 Labour Total: 714.00
 Sublet Total: 0.00
 Extras Total: 51.26

>>>> Claim Total: 808.12

Customer Signature: _____

Date: _____