

Pre-Authorization

Pre-Authorization number PA03698758		Reference no: 74075	Status: Approved	Approved by hull	Approved date 7/9/2024
Servicing Dealer	Name	Address	VIN	Retail sold on	

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGG18RW10496
------	----------------------	---	------------------

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201816A	Decorative Wood	0.00	0.20	0.20		1	0.10	Complaint:BATTEN STRIP ABOVE SINK IS HANGING DOWN FROM CEILING Cause:Plastic track that the batten strip secures to was bent. Straightened track and secured batten strip. Correction:Plastic track that the batten strip secures to was bent. Straightened track and secured batten strip.
2	3500208A	Vinyl Flooring - Re	0.00	0.20	0.20		1	0.60	Complaint:GLUE ON FLOOR IN FRONT OF BATHROOM Cause:Took a rag with mineral spirits and removed glue. Correction:Took a rag with mineral spirits and removed glue.
3	2300106A	Entrance Door - H	0.00	0.30	0.30		1	0.20	Complaint:ENTRY DOOR NEEDS ADJUSTED Cause:Placed a wood block at the top and bottom of the door and closed. Took a hammer and moved latch over from door. Door shuts easily. Correction:Placed a wood block at the top and bottom of the door and closed. Took a hammer and moved latch over from door. Door shuts easily.
4	2203314D	Sealant - Roof On	0.00	0.40	0.40		1	0.30	Complaint:ROOF NEEDS DICOR Cause:Applied dicor to roof as needed Correction:Applied dicor to roof as needed
Pre-Authorization number PA03698758					1.10				

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company