



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74227



CUSTOMER WORK ORDER

WO #: 74227 (Appointment Date: 15 JUL 2024 - Time: 11:00am)

Customer: 54931 - SERVICE, KAYLNN -
(618) 308-7852

Tag:

Author: PH

Location: 0718 CHECK CLAIMS

Stock #:

Stock Desc: 2021 TT KEYSTONE

HIDEOUT

Chassis #:

Serial #: 4YDT29025M7244511

Mileage:

Licence:

Invoice #: 407159

Date In: 15 JUL 24

Promised:

Date Sched:

Completed: 18 JUL 24

Warr. Date:

Job #REGULATOR - Warranty

COMPLAINT: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414
SECTION:71 COMPONENT:414 OPERATION:7141442B

CAUSE: lp regulator recall

CORRECTION: removed lp cover and looked at regulator model number and saw it was one of the ones that needed replaced and i removed old regulator and replaced with new

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	85.00

Parts

Part #	Description	Qty	Price	Total
696405	RECALL REGULATOR KIT W/HOSES - KEYSTONE	1.00	28.75	28.75

Subtotal for Job #REGULATOR: 113.75

Job #2 - External

COMPLAINT: THE REAR STABILIZER JACKS STOP WORKING INTERMITTANTLY.

CAUSE: find why rear jack is not working properly

CORRECTION: ran jack and jack would exstened but not retract after some testing i found the switch is bad and i got new switch and replaced and it is working properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
55-8174	CIRCUIT BREAKER-50A	1.00	N/C	N/C
387874	LIPPERT STAB JACK SWITCH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: CUSTOMER ADVISES THAT THE TONGUE JACK STOPS WORKING INTERMITTANTLY.



Customer #: 54931
SERVICE, KAYLNN



CAUSE: replace jack

CORRECTION: removed old jack because when running jack up it would amp out an not go up but it would go down so i removed old jack and wires then replaced with new jack and wired into box and tested to make sure it went up and down

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts				
Part #	Description	Qty	Price	Total
3291	3500# STROMBERG ELEC JACK -BULK	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: CHECK CONDITION OF BATTERY

CAUSE: test battery

CORRECTION: removed terminals from battery and put load tester on battery and it passed test then reconnected battery terminals

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Subtotal for Job #4: 0.00

Job #5 - External

CUSTOMER HAS SERVICE CONTRACT

Subtotal for Job #5: 0.00

Parts Total:	28.75
Labour Total:	85.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	113.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 18 Jul 2024



Customer #: 54931
SERVICE, KAYLNN

