

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74390
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50948 - DONALD H. BRADLEY, JR
Address: 949 OSAGE DR HENDERSON, KY

42420

Phone: 270-454-4853

Stock Number: 11307 - 2024 CATALINA 243RBSLE 5ZT2CANB1RU042729

VIN: 5ZT2CANB1RU042729 HIN: SER#: 5ZT2CANB1RU042729

Mileage: 0 Work Order Comp: 05 AUG 24

Auth. No: Dealer #:

Warr. Date: 12 APR 24 Work Order Date: 01 AUG 24 Inv #: 407852

WO # Job # Description JOB INFORMATION

74390 1 CUSTOMER ADVISES THAT THERE IS WATER RUNNING OUT FROM UNDER THE
SHOWER INTO THE FLOOR WHEN IN USE. CUSTOMER IS UNSURE WHERE THE
LEAK IS AT. WHEN LOOKING AT THE SHOWER, THE LEAK IS COMING FROM
THE LEFT SIDE. SEE BJ FOR EXACTE LOCATION
Shower

The two side glass panels leak over track when spraying water on
them.Siliconed the edges and the glass on both sides. Put a shim
under pan. Let dry and water test.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00

Excode Job# Description EXTRAS Qty Price Total

SS 1 SHOP SUPPLIES 1.00 0.00 0.00

Parts Total: 0.00

Labour Total: 34.00

Sublet Total: 0.00

Extras Total: 0.00

>>>> Claim Total: 34.00

Customer Signature: _____

Date: _____