



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74390
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74390 (Appointment Date: 01 AUG 2024 - Time: 09:30am)

Customer: 50948 - BRADLEY, JR,
DONALD H. - 270-454-4853

Tag:

Author: BJW

Location: 0802 CHECK STATUS WITH
BB

Stock #: 11307

Stock Desc: 2024 TT COACHMEN
CATALINA 243RBSLE

Chassis #: 5ZT2CANB1RU042729

Serial #: 5ZT2CANB1RU042729

Mileage:

Licence:

Invoice #:

Date In: 01 AUG 24

Promised: 31 AUG 24

Date Sched:

Completed: 05 AUG 24

Warr. Date: 12 APR 24

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THERE IS WATER RUNNING OUT FROM UNDER THE SHOWER INTO THE FLOOR WHEN IN USE. CUSTOMER IS UNSURE WHERE THE LEAK IS AT. WHEN LOOKING AT THE SHOWER, THE LEAK IS COMING FROM THE LEFT SIDE. SEE BJ FOR EXACTE LOCATION

CAUSE: Shower

CORRECTION: The two side glass panels leak over track when spraying water on them. Siliconed the edges and the glass on both sides. Put a shim under pan. Let dry and water test.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 34.00

Parts Total: 0.00
Labour Total: 34.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 34.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Aug 2024



Customer #: 50948
BRADLEY, JR, DONALD H.