



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74495
Promised Date: 17 AUG 24

CUSTOMER WORK ORDER

WO #: 74495

Customer: 55131 - WHITFIELD, BRADEN
- 812-664-0599

Tag:
Author: BH
Location: DELIVERY 0817

Stock #: 11407
Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX
Chassis #: 5ZT2CAEC7RK008234
Serial #: 5ZT2CAEC7RK008234
Mileage:
Licence:

Invoice #:
Date In: 10 AUG 24
Promised: 17 AUG 24
Date Sched:
Completed: 29 AUG 24
Warr. Date: 17 AUG 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Installed new battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked roof and awning. Checked power cord. Checked all interior lights. Checked converter output. Operated stab jacks. Checked TV and Radio. Performed LP drop test and set LP pressure at 11 in.wc. Checked Range and Refrigerator. Checked Water Heater on LP and Electric. Drained all holding tanks, including water heater. Retracted all stab jacks. Moved unit to wash bay area.

Labor Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 10K E2 EQUALIZER HITCH
New hitch setup on new truck and new camper

CORRECTION: Assembled hitch brackets and mounted in frame of unit.
Leveled the camper then set the hitch height on the vehicle. Assembled the hitch and adjusted as needed.
Tightened all hardware

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C



Customer #: 55131
WHITFIELD, BRADEN





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #E2:				0.00

Job #DELUXE - Internal

COMPLAINT: DELUXE STARTER KIT

CORRECTION: PUT IN UNIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: MONSTER MONSTER SEAL IN ALL TIRES

CORRECTION: Installed Monster Seal in all tires.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #MONSTER:			0.00

Job #1 - Internal

COMPLAINT: WASHBAY MAXXGAURD

CORRECTION: HAD WASHBAY APPLY

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: AC VENT FLAP BROKEN

CAUSE: AC VENT FLAP BROKEN

CORRECTION: One of the hinge pins is broken off of the flap. Turned in parts request. 8/16/24: Received new part. Removed broken ceiling plenum. Installed new ceiling plenum.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	17.00

Parts

Part #	Description	Qty	Price	Total
9271	GE MECHANICAL NON-DUCTED CEILING ASS	1.00	84.33	84.33

Subtotal for Job #2: 135.33



Parts Total: 84.33
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 135.33

W/O: 74495
Promised Date: 17 AUG 24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 29 Aug 2024

Customer Signature : _____

Customer Work Order



Customer #: 55131
WHITFIELD, BRADEN

