



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74501
Promised Date:
15 AUG 24



Customer #: 20036
MCKEON, DAWN



CUSTOMER WORK ORDER

WO #: 74501

Customer: 20036 - MCKEON, DAWN -
812-827-3077

Tag: BH - TV ORDERED. 8-12-24

Author: BH

Location: 0830 CHECK PREAUTH

Stock #: 11395

Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 269DBC

Chassis #: 4YDTSGM22R7105152

Serial #: 4YDTSGM22R7105152

Mileage:

Licence:

Invoice #:

Date In: 12 AUG 24

Promised: 15 AUG 24

Date Sched:

Completed: 23 AUG 24

Warr. Date: 15 AUG 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: final pdi

CORRECTION: did final and everything on sheet,also checked lp ,water,electrical,and appliances.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: swap customers hitch work

CORRECTION: took off brackets on old camper and installed on new camper,and i also had to move tank bracket back and remount.

SETUP HITCH HIGHT AND HOOKED UP TO TRAILER. I HAD TO CHANGED THE BALL SIZE AND ADD A SLEEVE TO THE DROP BAR. I PUT ALL OF THE HITCHWORK IN THE TRAILER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
14-0824	58102 2-1/2" TO 2" REDUCER SLEEVE	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00





Job #1 - Internal

COMPLAINT: INSTALL ROKU TV + SWING BRACKET TO FIT

CAUSE: mount tv and bracket

CORRECTION: had to measure and find center, drilled holes in panel, mounted bracket to tv and hung tv bracket and mounted to wall, had to make cable for tv.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	N/C
Parts				
Part #	Description	Qty	Price	Total
6578343	Roku - 32_ Class Select Series HD Sm	1.00	N/C	N/C
24-0121	TV Mount; Wall Mount; Extending Swi	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: FIX BATHDOOR GAP (WONT LATCH)

CAUSE: bathroom door wont latch

CORRECTION: took off cover and catch, measured for wood to shim out and cut wood and drilled hole for catch, installed and put cover on and secured and put on catch now door catches in hole and is secure.

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		DGH	85.00
Subtotal for Job #2:				85.00

Job #3 - Warranty

COMPLAINT: MAIN DOOR DOESNT CLOSE PROPERLY

CAUSE: entrance door

CORRECTION: took off catch and ground out and installed catch back and it shuts good now.

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		DGH	34.00
Subtotal for Job #3:				34.00

Job #4 - Warranty

COMPLAINT: FIX BUNK CURTAIN TRACK -PINCHED + KINKED

CAUSE: bunk curtain is pinched and track has akink in bend

CORRECTION: got curtain out and put in extra screw in bend of track.

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		DGH	34.00
Subtotal for Job #4:				34.00

Job #5 - Internal

COMPLAINT: SEE IF WE CAN ADD PLUG IN KITCHEN

CAUSE: add plug in in kitchen

CORRECTION: got plugin and breaker and clamp for electrical box, took off cover for electrical box and





pulled out,pulled out bottom drawer and vent for furnance,drilled holes in 2 walls to run wire measured out for box to go and tapped off cabinet and drilled hole and cut out shuare for box,installed hooked up wires to outlet and installed outlet to cabinet,ran wires through cabinets and hooked up wires to electrical box and breaker,installed breaker and tested outlet,then tied down wire all the way from one end to another.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts				
Part #	Description	Qty	Price	Total
72-7197	15 AMP DECOR RECEPTACLE WITH COVER - BLACK	1.00	N/C	N/C
671534	Breaker - 120V - 1P - 20A - THQP120 - 1/2" SP - GE	1.00	N/C	N/C
Subtotal for Job #5:				0.00

Job #6 - Warranty

COMPLAINT: BLACK TANK VALVE WONT SHUT ALL THE WAY

CAUSE: black tank valve wont shut all the way

CORRECTION: looked inside pipe and found glue was over seal and layin it to other side,had to pull apart blackand grey handle to get off,had to cut out glue on both sides,installed new seals because other ones were bad,put grey and black handles back on and secured,put water in both tanks to make sure no leaks,all good.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	136.00

Parts				
Part #	Description	Qty	Price	Total
11-0586	BLADEx VALVE SEALS, 3IN WITH HARDWAR	1.00	5.27	5.27
Subtotal for Job #6:				141.27

Parts Total:	5.27
Labour Total:	289.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	294.27

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Aug 2024

