



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74532
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74532

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0905 CHECK PREAUTH

Stock #: 11449
Stock Desc: 2025 TT FOREST RIVER
CHEROKEE GREY WOLF 26DBH
Chassis #: 4X4TCKB29SK091575
Serial #: 4X4TCKB29SK091575
Mileage: 0
Licence:

Invoice #:
Date In: 15 AUG 24
Promised: 31 AUG 24
Date Sched:
Completed: 31 AUG 24
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*74665 on 28 AUG 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: STEPS HITTING DOOR FRAME

CAUSE: Bracket was hitting door frame. Moved Bracket to clear.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: SCRATCHES ON DINETTE TABLE

CAUSE: Cleaned with mineral spirits.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 17.00

Job #3 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: The latch for the entry door was crooked. Straightened latch and tightened screws.

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: LIGHT COVER FELL OFF IN KITCHEN

CAUSE: Secured light cover.

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00

Subtotal for Job #4: 17.00

Job #5 - Warranty

COMPLAINT: GLUE ON FLOOR IN KITCHEN

CAUSE: Removed glue with mineral spirits and a rag

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	25.50

Subtotal for Job #5: 25.50

Job #6 - Warranty

COMPLAINT: REAR SCREEN DOOR HITTING LATCH

CAUSE: Moved latch over with hammer

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	8.50

Subtotal for Job #6: 8.50

Parts Total: 0.00
 Labour Total: 119.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 119.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Sep 2024

W/O: 74532
Promised Date: 31 AUG 24



Customer #: 1000
BASDENS AMERICAN RV,

