



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 74560



### CUSTOMER WORK ORDER

WO #: 74560

Customer: 26749 - BUEDEL, SCOTT D -  
812-774-2987

Tag:

Author: PH

Location: 0826 CHECK PREAUTH

Stock #: 11311

Stock Desc: 2024 TT COACHMEN

CATALINA 263BHCKLE

Chassis #: 5ZT2CARBXR030510

Serial #: 5ZT2CARBXR030510

Mileage:

Licence:

Invoice #:

Date In: 19 AUG 24

Promised:

Date Sched:

Completed: 23 AUG 24

Warr. Date: 16 MAR 24

#### Job #1 - External

COMPLAINT: Transferred to BAS\*74569 on 19 AUG 24

Estimate amount was 0.00

CUSTOMERS 7 WAY WAS DRAGGED AND HE HAD TO SPLICE IT TO FINISH HIS TRIP. HE SAID HE SAY SPARKS AND HIS BRAKES STOPPED WORKING. INSTALL NEW 7 WAY CORD AND TEST EVERYTHING.

CORRECTION: I HAD TO CUT OPEN THE UNDER BELLY AT THE POINT WHERE THE WIRING GOES INTO IT. I FOUND THE JUNCTION BOX AND REMOVED THE 7-WAY CORD FROM IT. I INSTALLED A NEW 7-WAY CORD AND TESTED IT. I SEALED UP THE UNDER BELLY AFTER TESTING.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #1: 0.00**

#### Job #2 - Warranty

COMPLAINT: HALF OF THE MARKER LIGHTS ARE NOT WORKING ON THE UNIT

CORRECTION: I FOUND ONE OF THE CONNECTORS BEHIND THE RIGHT REAR TAIL LIGHT HAD GOTTEN HOT. IT MELTED THE CONNECTOR AND I REPLACE ALL 3 CONNECTORS AT THIS LOCATION.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	102.00

**Subtotal for Job #2: 102.00**

Customer #: 26749  
BUEDEL, SCOTT D



W/O: 74560

Parts Total:	0.00
Labour Total:	102.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>102.00</b>


Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 23 Aug 2024

Customer Signature : \_\_\_\_\_

Customer Work Order



Customer #: 26749  
BUDEL, SCOTT D

