

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74570
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 2105R - 2024 SPRINGDALE 1800BH 4YDTSGG16RW102280

VIN: 4YDTSGG16RW102280 HIN: SER#: 4YDTSGG16RW102280

Mileage: 0 Work Order Comp: 27 AUG 24

Auth. No: Dealer #: 1194

Warr. Date: Work Order Date: 19 AUG 24 Inv #: 408681

WO # Job # Description JOB INFORMATION

74570 1 TODD ADVISED THAT THERE IS WATER LEAKING DOWN FROM THE A/C UNIT
INTO THE BED AND THE FLOOR.

Drain hole was clogged

Inspected the ac in the wall. Noticed the floor of the ac was
full of water. When the ac was on the fan would kick the water
out of the ac. This causing water to be splashed the the hole for
the electrical cord and onto the bed. Unplugged the ac then
unscrewed the trim and ac from the wall. Pulled out the ac then
inspected the bottom of the ac, found the drain hole clogged with
debree. Cleaned out the hole of debree. Mounted the ac back in
the wall and plugged in the power. Now ac can drain off the
condensation. Powered on the ac and let it run. Checked the ac
the following morning, found no pool of water.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISCELLANEOUS REPAIR 0.00 170.00 0.00

Z990 1 MISCELLANEOUS REPAIR 1.00 170.00 170.00

Z990 1 MISCELLANEOUS REPAIR 0.00 170.00 0.00

Parts Total: 0.00

Labour Total: 170.00

Sublet Total: 0.00

Extras Total: 0.00

>>>> Claim Total: 170.00

Customer Signature: _____

Date: _____